



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 11.OCT.2022 10:11:59

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 11.OCT.2022 10:12:13

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 11.OCT.2022 10:12:28

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 11.OCT.2022 10:12:42

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 11.OCT.2022 10:13:00

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 11.OCT.2022 10:13:17

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 11.OCT.2022 10:14:22

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 11.OCT.2022 10:14:36

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 11.OCT.2022 10:14:51

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 11.OCT.2022 10:15:05

Band 2_3 MHz_High_QPSK_RB15#0




Date: 11.OCT.2022 10:15:20

Band 2_3 MHz_High_16QAM_RB15#0




Date: 11.OCT.2022 10:15:34

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 10:16:47

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 10:17:05

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 11.OCT.2022 10:19:10

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 11.OCT.2022 10:19:25

Band 2_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 10:19:44

Band 2_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 10:20:02

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 10:21:13

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 10:21:29

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 11.OCT.2022 10:21:48

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 11.OCT.2022 10:22:03

Band 2_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 10:22:23

Band 2_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 10:22:38

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 11.OCT.2022 10:23:36

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 11.OCT.2022 10:23:57

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 11.OCT.2022 10:24:19

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 11.OCT.2022 10:24:43

Band 2_15 MHz_High_QPSK_RB75#0




Date: 11.OCT.2022 10:25:08

Band 2_15 MHz_High_16QAM_RB75#0




Date: 11.OCT.2022 10:25:29

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 11.OCT.2022 10:26:27

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 11.OCT.2022 10:26:48

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 11.OCT.2022 10:27:07

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 11.OCT.2022 10:27:26

Band 2_20 MHz_High_QPSK_RB100#0




Date: 11.OCT.2022 10:27:48

Band 2_20 MHz_High_16QAM_RB100#0




Date: 11.OCT.2022 10:28:06

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 11.OCT.2022 10:28:29

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 11.OCT.2022 10:28:46

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 11.OCT.2022 10:29:04

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 11.OCT.2022 10:29:18

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 11.OCT.2022 10:29:33

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 11.OCT.2022 10:29:50

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 11.OCT.2022 10:31:00

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 11.OCT.2022 10:31:15

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 11.OCT.2022 10:31:33

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 11.OCT.2022 10:31:47

Band 4_3 MHz_High_QPSK_RB15#0




Date: 11.OCT.2022 10:32:05

Band 4_3 MHz_High_16QAM_RB15#0




Date: 11.OCT.2022 10:32:19

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 10:33:02

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 10:33:20

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 11.OCT.2022 10:33:38

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 11.OCT.2022 10:33:53

Band 4_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 10:34:12

Band 4_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 10:34:29

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 10:35:36

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 10:35:52

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 11.OCT.2022 10:36:11

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 11.OCT.2022 10:36:26

Band 4_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 10:36:46

Band 4_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 10:37:04

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 11.OCT.2022 10:37:50

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 11.OCT.2022 10:38:11

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 11.OCT.2022 10:38:30

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 11.OCT.2022 10:38:51

Band 4_15 MHz_High_QPSK_RB75#0




Date: 11.OCT.2022 10:39:13

Band 4_15 MHz_High_16QAM_RB75#0




Date: 11.OCT.2022 10:39:30

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 11.OCT.2022 10:40:15

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 11.OCT.2022 10:40:37

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 11.OCT.2022 10:40:59

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 11.OCT.2022 10:41:20

Band 4_20 MHz_High_QPSK_RB100#0




Date: 11.OCT.2022 10:41:43

Band 4_20 MHz_High_16QAM_RB100#0




Date: 11.OCT.2022 10:42:04

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 10:42:31

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 10:42:52

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 11.OCT.2022 10:43:13

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 11.OCT.2022 10:43:34

Band 7_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 10:43:53

Band 7_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 10:44:11

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 10:45:13

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 10:45:32

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 11.OCT.2022 10:45:51

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 11.OCT.2022 10:46:10

Band 7_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 10:46:29

Band 7_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 10:46:48

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 11.OCT.2022 10:47:35

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 11.OCT.2022 10:47:56

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 11.OCT.2022 10:48:18

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 11.OCT.2022 10:48:39

Band 7_15 MHz_High_QPSK_RB75#0




Date: 11.OCT.2022 10:49:01

Band 7_15 MHz_High_16QAM_RB75#0




Date: 11.OCT.2022 10:49:25

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 11.OCT.2022 10:50:19

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 11.OCT.2022 10:50:40

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 11.OCT.2022 10:51:03

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 11.OCT.2022 10:51:27

Band 7_20 MHz_High_QPSK_RB100#0




Date: 11.OCT.2022 10:51:49

Band 7_20 MHz_High_16QAM_RB100#0




Date: 11.OCT.2022 10:52:11

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 11.OCT.2022 13:04:49

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 11.OCT.2022 13:05:03

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 11.OCT.2022 13:05:21

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 11.OCT.2022 13:05:38

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 11.OCT.2022 13:05:56

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 11.OCT.2022 13:06:13

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 11.OCT.2022 13:06:59

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 11.OCT.2022 13:07:17

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 11.OCT.2022 13:07:32

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 11.OCT.2022 13:07:49

Band 5_3 MHz_High_QPSK_RB15#0




Date: 11.OCT.2022 13:08:04

Band 5_3 MHz_High_16QAM_RB15#0




Date: 11.OCT.2022 13:08:18

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 13:09:02

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 13:09:20

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 11.OCT.2022 13:09:38

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 11.OCT.2022 13:09:56

Band 5_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 13:10:15

Band 5_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 13:10:33

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 13:12:33

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 13:12:52

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 11.OCT.2022 13:13:12

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 11.OCT.2022 13:13:33

Band 5_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 13:13:53

Band 5_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 13:14:11

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 11.OCT.2022 13:14:34

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 11.OCT.2022 13:14:48

Band 12_1.4 MHz_Middle_QPSK_RB6#0




Date: 11.OCT.2022 13:15:09

Band 12_1.4 MHz_Middle_16QAM_RB6#0




Date: 11.OCT.2022 13:15:26

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 11.OCT.2022 13:15:41

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 11.OCT.2022 13:15:58

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 11.OCT.2022 13:17:08

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 11.OCT.2022 13:17:22

Band 12_3 MHz_Middle_QPSK_RB15#0




Date: 11.OCT.2022 13:17:36

Band 12_3 MHz_Middle_16QAM_RB15#0




Date: 11.OCT.2022 13:17:53

Band 12_3 MHz_High_QPSK_RB15#0




Date: 11.OCT.2022 13:18:07

Band 12_3 MHz_High_16QAM_RB15#0




Date: 11.OCT.2022 13:18:20

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 13:19:09

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 13:19:27

Band 12_5 MHz_Middle_QPSK_RB25#0




Date: 11.OCT.2022 13:19:44

Band 12_5 MHz_Middle_16QAM_RB25#0




Date: 11.OCT.2022 13:19:58

Band 12_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 13:20:19

Band 12_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 13:20:36

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 13:24:53

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 13:25:12

Band 12_10 MHz_Middle_QPSK_RB50#0




Date: 11.OCT.2022 13:25:31

Band 12_10 MHz_Middle_16QAM_RB50#0




Date: 11.OCT.2022 13:25:50

Band 12_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 13:26:12

Band 12_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 13:26:28

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 13:28:02

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 13:28:20

Band 17_5 MHz_Middle_QPSK_RB25#0




Date: 11.OCT.2022 13:28:36

Band 17_5 MHz_Middle_16QAM_RB25#0




Date: 11.OCT.2022 13:28:54

Band 17_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 13:29:13

Band 17_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 13:29:30

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 13:30:14

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 13:30:29

Band 17_10 MHz_Middle_QPSK_RB50#0




Date: 11.OCT.2022 13:30:49

Band 17_10 MHz_Middle_16QAM_RB50#0




Date: 11.OCT.2022 13:31:07

Band 17_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 13:31:26

Band 17_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 13:31:45

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 14:19:07

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 14:19:26

Band 38_5 MHz_Middle_QPSK_RB25#0




Date: 11.OCT.2022 14:19:50

Band 38_5 MHz_Middle_16QAM_RB25#0




Date: 11.OCT.2022 14:20:18

Band 38_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 14:20:42

Band 38_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 14:21:03

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 14:22:38

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 14:22:59

Band 38_10 MHz_Middle_QPSK_RB50#0




Date: 11.OCT.2022 14:23:28

Band 38_10 MHz_Middle_16QAM_RB50#0




Date: 11.OCT.2022 14:23:50

Band 38_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 14:24:16

Band 38_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 14:24:41

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 11.OCT.2022 14:27:58

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 11.OCT.2022 14:28:32

Band 38_15 MHz_Middle_QPSK_RB75#0




Date: 11.OCT.2022 14:29:07

Band 38_15 MHz_Middle_16QAM_RB75#0




Date: 11.OCT.2022 14:29:47

Band 38_15 MHz_High_QPSK_RB75#0




Date: 11.OCT.2022 14:30:15

Band 38_15 MHz_High_16QAM_RB75#0




Date: 11.OCT.2022 14:30:42

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 11.OCT.2022 14:31:59

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 11.OCT.2022 14:32:23

Band 38_20 MHz_Middle_QPSK_RB100#0




Date: 11.OCT.2022 14:32:49

Band 38_20 MHz_Middle_16QAM_RB100#0




Date: 11.OCT.2022 14:33:17

Band 38_20 MHz_High_QPSK_RB100#0




Date: 11.OCT.2022 14:33:45

Band 38_20 MHz_High_16QAM_RB100#0




Date: 11.OCT.2022 14:34:13

Band 40 Lower_5 MHz_Low_QPSK_RB25#0




Date: 8.NOV.2022 16:19:09

Band 40 Lower_5 MHz_Low_16QAM_RB25#0




Date: 8.NOV.2022 16:19:34

Band 40 Lower_5 MHz_Middle_QPSK_RB25#0




Date: 8.NOV.2022 16:19:53

Band 40 Lower_5 MHz_Middle_16QAM_RB25#0




Date: 8.NOV.2022 16:20:28

Band 40 Lower_10 MHz_Middle_QPSK_RB50#0




Date: 8.NOV.2022 16:21:49

Band 40 Lower_10 MHz_Middle_16QAM_RB50#0




Date: 8.NOV.2022 16:22:15

Band 40 Upper_5 MHz_Low_QPSK_RB25#0




Date: 8.NOV.2022 16:53:10

Band 40 Upper_5 MHz_Low_16QAM_RB25#0




Date: 8.NOV.2022 16:53:39

Band 40 Upper_5 MHz_Middle_QPSK_RB25#0




Date: 8.NOV.2022 16:54:18

Band 40 Upper_5 MHz_Middle_16QAM_RB25#0




Date: 8.NOV.2022 16:54:43

Band 40 Upper_5 MHz_High_QPSK_RB25#0




Date: 8.NOV.2022 16:55:09

Band 40 Upper_5 MHz_High_16QAM_RB25#0




Date: 8.NOV.2022 16:55:31

Band 40 Upper_10 MHz_Middle_QPSK_RB50#0




Date: 8.NOV.2022 16:56:06

Band 40 Upper_10 MHz_Middle_16QAM_RB50#0




Date: 8.NOV.2022 16:56:30

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 16:09:48

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 16:10:15

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 11.OCT.2022 16:10:43

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 11.OCT.2022 16:11:07

Band 41_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 16:11:32

Band 41_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 16:12:06

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 16:12:33

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 16:12:55

Band 41_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 16:14:07

Band 41_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 16:14:26

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 11.OCT.2022 16:15:07

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 11.OCT.2022 16:15:31

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 11.OCT.2022 16:16:02

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 11.OCT.2022 16:16:45

Band 41_15 MHz_High_QPSK_RB75#0




Date: 11.OCT.2022 16:17:26

Band 41_15 MHz_High_16QAM_RB75#0




Date: 11.OCT.2022 16:17:56

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 11.OCT.2022 16:18:33

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 11.OCT.2022 16:19:04

Band 41_20 MHz_Middle_QPSK_RB100#0




Date: 11.OCT.2022 16:19:30

Band 41_20 MHz_Middle_16QAM_RB100#0




Date: 11.OCT.2022 16:19:51

Band 41_20 MHz_High_QPSK_RB100#0



Date: 11.OCT.2022 16:20:23

Band 41_20 MHz_High_16QAM_RB100#0



Date: 11.OCT.2022 16:20:47