



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 11.OCT.2022 10:55:04

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 11.OCT.2022 10:55:11

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 11.OCT.2022 10:55:18

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 11.OCT.2022 10:55:25

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 11.OCT.2022 10:59:31

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 11.OCT.2022 10:59:37

Band 2_3 MHz_High_QPSK_RB15#0




Date: 11.OCT.2022 10:59:45

Band 2_3 MHz_High_16QAM_RB15#0




Date: 11.OCT.2022 10:59:52

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 11:00:31

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 11:00:37

Band 2_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 11:00:45

Band 2_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 11:00:53

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 11:01:32

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 11:01:40

Band 2_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 11:01:49

Band 2_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 11:01:56

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 11.OCT.2022 11:02:44

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 11.OCT.2022 11:02:51

Band 2_15 MHz_High_QPSK_RB75#0




Date: 11.OCT.2022 11:02:59

Band 2_15 MHz_High_16QAM_RB75#0




Date: 11.OCT.2022 11:03:06

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 11.OCT.2022 11:03:52

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 11.OCT.2022 11:03:59

Band 2_20 MHz_High_QPSK_RB100#0




Date: 11.OCT.2022 11:04:07

Band 2_20 MHz_High_16QAM_RB100#0




Date: 11.OCT.2022 11:04:14

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 11.OCT.2022 11:04:27

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 11.OCT.2022 11:04:34

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 11.OCT.2022 11:04:40

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 11.OCT.2022 11:04:46

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 11.OCT.2022 11:05:24

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 11.OCT.2022 11:05:31

Band 4_3 MHz_High_QPSK_RB15#0




Date: 11.OCT.2022 11:05:37

Band 4_3 MHz_High_16QAM_RB15#0




Date: 11.OCT.2022 11:05:43

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 11:06:48

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 11:06:56

Band 4_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 11:07:03

Band 4_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 11:07:10

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 11:07:43

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 11:07:51

Band 4_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 11:07:59

Band 4_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 11:08:07

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 11.OCT.2022 11:09:31

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 11.OCT.2022 11:09:37

Band 4_15 MHz_High_QPSK_RB75#0




Date: 11.OCT.2022 11:09:45

Band 4_15 MHz_High_16QAM_RB75#0




Date: 11.OCT.2022 11:09:52

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 11.OCT.2022 11:10:31

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 11.OCT.2022 11:10:39

Band 4_20 MHz_High_QPSK_RB100#0




Date: 11.OCT.2022 11:10:47

Band 4_20 MHz_High_16QAM_RB100#0




Date: 11.OCT.2022 11:10:54

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 17:22:00

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 17:22:14

Band 7_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 17:21:19

Band 7_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 17:21:39

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 17:23:13

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 17:23:26

Band 7_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 17:23:55

Band 7_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 17:24:08

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 11.OCT.2022 17:24:54

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 11.OCT.2022 17:25:06

Band 7_15 MHz_High_QPSK_RB75#0




Date: 11.OCT.2022 17:25:29

Band 7_15 MHz_High_16QAM_RB75#0




Date: 11.OCT.2022 17:25:41

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 11.OCT.2022 17:26:14

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 11.OCT.2022 17:26:28

Band 7_20 MHz_High_QPSK_RB100#0




Date: 11.OCT.2022 17:26:50

Band 7_20 MHz_High_16QAM_RB100#0




Date: 11.OCT.2022 17:27:06

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 11.OCT.2022 13:33:54

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 11.OCT.2022 13:34:00

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 11.OCT.2022 13:34:07

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 11.OCT.2022 13:34:14

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 11.OCT.2022 13:36:12

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 11.OCT.2022 13:36:19

Band 5_3 MHz_High_QPSK_RB15#0




Date: 11.OCT.2022 13:36:26

Band 5_3 MHz_High_16QAM_RB15#0




Date: 11.OCT.2022 13:36:34

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 13:37:13

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 13:37:20

Band 5_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 13:37:27

Band 5_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 13:37:34

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 13:38:19

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 13:38:26

Band 5_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 13:38:35

Band 5_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 13:38:43

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 11.OCT.2022 13:38:55

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 11.OCT.2022 13:39:02

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 11.OCT.2022 13:39:09

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 11.OCT.2022 13:39:15

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 11.OCT.2022 13:40:19

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 11.OCT.2022 13:40:26

Band 12_3 MHz_High_QPSK_RB15#0




Date: 11.OCT.2022 13:40:33

Band 12_3 MHz_High_16QAM_RB15#0




Date: 11.OCT.2022 13:40:39

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 13:41:12

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 13:41:19

Band 12_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 13:41:26

Band 12_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 13:41:33

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 13:42:06

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 13:42:14

Band 12_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 13:42:22

Band 12_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 13:42:29

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 13:42:42

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 13:42:50

Band 17_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 13:42:57

Band 17_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 13:43:03

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 13:43:40

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 13:43:48

Band 17_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 13:43:56

Band 17_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 13:44:03

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 18:15:05

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 18:15:29

Band 38_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 18:15:55

Band 38_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 18:16:10

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 18:18:42

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 18:19:08

Band 38_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 18:19:41

Band 38_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 18:20:26

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 11.OCT.2022 18:21:16

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 11.OCT.2022 18:21:54

Band 38_15 MHz_High_QPSK_RB75#0




Date: 11.OCT.2022 18:22:22

Band 38_15 MHz_High_16QAM_RB75#0




Date: 11.OCT.2022 18:22:46

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 11.OCT.2022 18:23:24

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 11.OCT.2022 18:23:53

Band 38_20 MHz_High_QPSK_RB100#0




Date: 11.OCT.2022 18:24:12

Band 38_20 MHz_High_16QAM_RB100#0




Date: 11.OCT.2022 18:24:56

LTE Band 40 (2305~2315MHz) Bandedge 5MHz-Low CH-QPSK




Date: 8.NOV.2022 14:57:11

LTE Band 40 (2305~2315MHz) Bandedge 5MHz-Low CH-16QAM




Date: 8.NOV.2022 14:57:53

LTE Band 40 (2305~2315MHz) Bandedge 5MHz-High CH-QPSK




Date: 8.NOV.2022 14:58:58

LTE Band 40 (2305~2315MHz) Bandedge 5MHz-High CH-16QAM




Date: 8.NOV.2022 14:59:41

LTE Band 40 (2305~2315MHz) Bandedge 10MHz-Middle CH-QPSK



Date: 8.NOV.2022 15:00:18

LTE Band 40 (2305~2315MHz) Bandedge 10MHz-Middle CH-16QAM




Date: 8.NOV.2022 15:01:10

LTE Band 40 (2350~2360MHz) Bandedge 5MHz-Low CH-QPSK



* RBW 100 kHz
* VBW 300 kHz
* SWT 10 s




Date: 8.NOV.2022 15:04:52

LTE Band 40 (2350~2360MHz) Bandedge 5MHz-Low CH-16QAM




* RBW 100 kHz
* VBW 300 kHz
* SWT 10 s




Date: 8.NOV.2022 15:05:55

LTE Band 40 (2350~2360MHz) Bandedge 5MHz-High CH-QPSK




Date: 8.NOV.2022 15:07:29

LTE Band 40 (2350~2360MHz) Bandedge 5MHz-High CH-16QAM




Date: 8.NOV.2022 15:08:41

LTE Band 40 (2350~2360MHz) Bandedge 10MHz-Middle CH-QPSK




Date: 8.NOV.2022 15:10:18

LTE Band 40 (2350~2360MHz) Bandedge 10MHz-Middle CH-16QAM




Date: 8.NOV.2022 15:11:08

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 11.OCT.2022 16:46:59

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 11.OCT.2022 16:47:19

Band 41_5 MHz_High_QPSK_RB25#0




Date: 11.OCT.2022 16:47:50

Band 41_5 MHz_High_16QAM_RB25#0




Date: 11.OCT.2022 16:48:02

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 11.OCT.2022 16:49:08

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 11.OCT.2022 16:49:21

Band 41_10 MHz_High_QPSK_RB50#0




Date: 11.OCT.2022 16:49:42

Band 41_10 MHz_High_16QAM_RB50#0




Date: 11.OCT.2022 16:49:56

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 11.OCT.2022 16:59:41

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 11.OCT.2022 16:59:57

Band 41_15 MHz_High_QPSK_RB75#0




Date: 11.OCT.2022 17:01:38

Band 41_15 MHz_High_16QAM_RB75#0




Date: 11.OCT.2022 17:02:05

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 11.OCT.2022 17:06:35

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 11.OCT.2022 17:06:52

Band 41_20 MHz_High_QPSK_RB100#0



Date: 11.OCT.2022 17:02:56

Band 41_20 MHz_High_16QAM_RB100#0



Date: 11.OCT.2022 17:03:12