

# ADB40S2AN, ADBB0S2KN

## FCC/IC LABEL Information

Hyundai MOBIS Co., Ltd.	
<b>FCC ID:</b>	<b>TQ8-ADB40S2AN</b>
<b>Contains FCC ID:</b>	<b>LHJ-CASAN</b>
<b>IC:</b>	<b>5074A-ADBB0S2KN</b>
<b>IC MODEL:</b>	<b>ADBB0S2KN</b>
<b>Contains IC:</b>	<b>7414C-BK1000</b>

---

This device complies with part 15 of the FCC rules  
Operation is subject to the following two conditions:  
(1) This device may not cause harmful interference, and  
(2) This device must accept any interference received,  
including interference that may cause undesired  
operation.

---

MANUFACTURED BY HYUNDAI MOBIS

### PRODUCT LABEL

### LABEL LOCATION

