


ADBB0D5AN, ADBB0D5KN

FCC/IC LABEL Information

Hyundai MOBIS Co., Ltd.	
FCC ID:	TQ8-ADBB0D5AN
Contains FCC ID:	LHJ-CASAN
IC:	5074A-ADBB0D5KN
IC MODEL:	ADBB0D5KN
Contains IC:	7414C-BK1000
<hr/>	
This device complies with part 15 of the FCC rules Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.	
<hr/>	
MANUFACTURED BY HYUNDAI MOBIS	

PRODUCT LABEL

LABEL LOCATION



ADBB0A8KN

IC LABEL Information

Hyundai MOBIS Co., Ltd.	
FCC ID:	TQ8-ADBB0D5AN
Contains FCC ID:	LHJ-CASAN
IC:	5074A-ADBB0D5KN
IC MODEL:	ADBB0A8KN
Contains IC:	7414C-BK1000
<hr/>	
This device complies with part 15 of the FCC rules Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.	
<hr/>	
MANUFACTURED BY HYUNDAI MOBIS	

PRODUCT LABEL

LABEL LOCATION

