

HCT Co., Ltd. 74, Seoicheon-ro 578beon-gil, Majang-myeon, Icheon-si, Gyeonggi-do, 17383 KOREA Tel. +82 31 634 6300 Fax. +82 31 645 6401

Appendix A: Test Setup Photo FCC ID/IC. TQ8-ATB41HSAN / 5074A-ATB41HSKN

File No. HCT-RF-2003-FI006-P HCT-RF-2003-FI007-P HCT-RF-2003-FI008-P HCT-RF-2003-FI009-P

REVISION HISTORY


The revision history for this document is shown in table.

| Revision No. | Date of Issue | Description |
|--------------|----------------|-----------------|
| 0 | March 20, 2020 | Initial Release |




1. Radiated Test Setup Photo


Radiated spurious emissions & Restricted Band Edge (Above 1 GHz)



HCT-RF-2003-FI006-P











Radiated spurious emissions (Below 1GHz)









2. Conducted Test Setup Photo



HCT-RF-2003-FI006-P

HCT-RF-2003-FI007-P HCT-RF-2003-FI008-P





3. DFS Test Setup Photo

