




Label Information

1. Label drawing

<p>Part No. : 96560 R5720 Model : ATC32HYAN</p> <p>HW ver : 0</p> <p>14.4 V, 10A</p> <p>FCC ID : TQ8-ATC32HYAN Contains FCC ID: YZP-VL3000</p> <p>14.4V  10A</p>	<p>HYUNDAI MOBIS</p>
	
<p>Made in Korea Hyundai MOBIS Co., Ltd.</p>	



Label Information

1. Label drawing

<p>Part No. : 96560 P4720</p> <p>Model : ATC32HCAN</p> <p>HW ver : 0</p> <p>14.4 V, 4 Ω, 10 A</p> <p>FCC ID : TQ8-ATC32HYAN Contains FCC ID: YZP-VL3000</p> <p>14.4V \equiv 10A</p>	<p>HYUNDAI MOBIS</p>
	
<p>Made in Korea</p>	<p>Hyundai MOBIS Co., Ltd.</p>

Label Information

1. Label drawing

<p>Part No. : 96560 P4920 Model : ATC35HCAN</p> <p>HW ver : 0</p> <p>14.4 V, 4 Ω, 10 A</p> <p>FCC ID : TQ8-ATC32HYAN Contains FCC ID: YZP-VL3000</p> <p>14.4V  10A</p>	<p>HYUNDAI MOBIS</p>
	
<p>Made in Korea Hyundai MOBIS Co., Ltd.</p>	

2. Label location

