


# FCC LABEL Information

**Model Name: DA330GKAN, DA330J9AN, DA331J9AN, DA330J9GG, DA331J9GG, DA332J9GG, DA333J9GG, DA330J9MG, DA330J9UA, DA330J9EG, DA330J9EP, DA335J9EP, DA331J9EP, DA332J9EP, DA333J9EP, DA334J9EP**

## LABEL LOCATION

|   |                      |
|---|----------------------|
| <b>Hyundai MOBIS Co., Ltd.</b>  |                      |
| <b>FCC ID:</b>  | <b>TQ8-DA330GKAN</b> |
| <b>Contains FCC ID:</b>   | <b>YZP-VL3010</b>    |
| <hr/>   |                      |
| This device complies with part 15 of the FCC rules<br>Operation is subject to the following two conditions:<br>(1) This device may not cause harmful interference, and<br>(2) This device must accept any interference received,<br>including interference that may cause undesired<br>operation. |                      |
| <hr/>   |                      |
| MANUFACTURED BY HYUNDAI MOBIS   |                      |

## PRODUCT LABEL



**FRONT TOP**