



# Label Location

Part No :		
Model : VT250TWAN		
HW ver :	Frequency range:	MHz
V, Ω, A		kHz
FCC ID: TQ8-VT250TWAN	프린팅 영역(33X10)	
Contains FCC ID : YZP-VL3000	: 승인번호 ONLY	
[Large empty rectangular area for label placement]		
This device complies with part 15 of the FCC Rules. Operation is Subject to the following two conditions : (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation		
[Small empty rectangular area] [Small empty rectangular area] HYUNDAI MOBIS Co., Ltd		



Part No :  
Model : VT250JWAN  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT250TWAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
Model : VT251JWAN  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT250TWAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
Model : VT260TWAN  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT250TWAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
Model : VT260JWAN  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT250TWAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
Model : VT261JWAN  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT250TWAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
Model : VT261TWAN  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT250TWAN

프린팅 영역(33X10)


Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
 Model : VT262JWAN  
 HW ver : V, Ω, A  
 Frequency range: MHz  
 kHz




FCC ID: TQ8-VT250TWAN	프린팅 영역(33X10)
Contains FCC ID : YZP-VL3000	: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
 Operation is Subject to the following two conditions :  
 (1) this device may not cause harmful interference, and  
 (2) this device must accept any interference received,  
 including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
 Model : VT263JWAN  
 HW ver : V, Ω, A  
 Frequency range: MHz  
 kHz



FCC ID: TQ8-VT250TWAN	프린팅 영역(33X10)
Contains FCC ID : YZP-VL3000	: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
 Operation is Subject to the following two conditions :  
 (1) this device may not cause harmful interference, and  
 (2) this device must accept any interference received,  
 including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd