



# Label Location

Part No :		
Model : WU3711UBO		
HW ver :	Frequency range:	MHz
V, Ω, A		kHz
FCC ID: TQ8-VT2600TAN	프린팅 영역(33X10)	
Contains FCC ID : YZP-VL3000	: 승인번호 ONLY	
This device complies with part 15 of the FCC Rules. Operation is Subject to the following two conditions : (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation		
		HYUNDAI MOBIS Co., Ltd



Part No :  
Model : WU3731UBO  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
Model : WU3721UBO  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
Model : WU371UP BO  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
Model : WU3611UBO  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
Model : WU3631UBO  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :  
Model : WU3621UBO  
HW ver :  
V, Ω, A



Frequency range: MHz  
kHz

FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.  
Operation is Subject to the following two conditions :  
(1) this device may not cause harmful interference, and  
(2) this device must accept any interference received,  
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

