



Tune Up Procedure

Kingfisher 40W 1900MHz CDMA SCPA

Product # 100.0195.001

Unity Wireless Systems Corp.

Date: May 17, 2006

Report No.: 170506.1

Labs: 19473 Fraser Way, Pitt Meadows, BC, Canada V3Y 2V4

A handwritten signature in blue ink, appearing to read "B. Balston".

Bruce Balston
EMC Engineer

A handwritten signature in blue ink, appearing to read "Andrew Marles".

Andrew Marles
EMC Coordinator

A.1 Tune Up Procedure

2.3.2 Tune Up Procedure

- Attach RF power meter and load to RF output port of PA
- Attach RF source to the input port of PA



Before applying DC power to the PA be sure it's output is connected to the appropriate load and the input power level is set to minimum in order to prevent RF overdrive.

- Apply DC power to PA
- Adjust RF input level to the desired level, making sure that the output power does not exceed the maximum rated level for the Kingfisher SCPA (40W).