



Annex B of test report F101336E4
EUT: cB-OBC001i
Manufacturer: connectBlue AB




101336_a.jpg cB-OBC001i, top view

Annex B of test report F101336E4
EUT: cB-OBC001i
Manufacturer: connectBlue AB



101336_c.jpg cB-OBC001i, top view, shielding removed

Annex B of test report F101336E4
EUT: cB-OBC001i
Manufacturer: connectBlue AB



101336_b.jpg cB-OBC001i, bottom view


Annex B of test report F101336E4
EUT: cB-OBC001i
Manufacturer: connectBlue AB



101336_g.jpg

cB-OBC001i, mounted on carrier board (cB-0942), top view

Annex B of test report F101336E4
EUT: cB-OBC001i
Manufacturer: connectBlue AB



101336_f.jpg cB-OBC001i, carrier board (cB-0942), bottom view