



Date: 14.FEB.2019 16:10:34

Band26_5MHz_16QAM_26815_25RB#0




Date: 14.FEB.2019 16:02:28

Band26_5MHz_16QAM_27015_25RB#0




Date: 14.FEB.2019 16:08:51

Band26_10MHz_QPSK_26840_1RB#0




Date: 14.FEB.2019 16:15:07

Band26_10MHz_QPSK_26990_1RB#49




Date: 14.FEB.2019 16:19:25

Band26_10MHz_QPSK_26840_50RB#0




Date: 14.FEB.2019 16:13:29

Band26_10MHz_QPSK_26990_50RB#0




Date: 14.FEB.2019 16:16:47

Band26_10MHz_16QAM_26840_1RB#0




Date: 14.FEB.2019 16:15:39

Band26_10MHz_16QAM_26990_1RB#49




Date: 14.FEB.2019 16:16:41

Band26_10MHz_16QAM_26840_50RB#0




Band26_10MHz_16QAM_26990_50RB#0



Band26_15MHz_QPSK_26865_1RB#0




Band26_15MHz_QPSK_26965_1RB#74




Date: 14.FEB.2019 16:35:41

Band26_15MHz_QPSK_26865_75RB#0




Date: 14.FEB.2019 16:29:45

Band26_15MHz_QPSK_26965_75RB#0




Date: 14.FEB.2019 16:35:00


Band26_15MHz_16QAM_26865_1RB#0




Band26_15MHz_16QAM_26965_1RB#74




Band26_15MHz_16QAM_26865_75RB#0



Band26_15MHz_16QAM_26965_75RB#0




Band38_5MHz_QPSK_37775_1RB#0




Date: 13.FEB.2019 16:36:14

Band38_5MHz_QPSK_38225_1RB#24




Date: 13.FEB.2019 16:39:27

Band38_5MHz_QPSK_37775_25RB#0




Date: 13.FEB.2019 16:37:24

Band38_5MHz_QPSK_38225_25RB#0




Date: 13.FEB.2019 16:39:57

Band38_5MHz_16QAM_37775_1RB#0




Date: 13.FEB.2019 16:34:24

Band38_5MHz_16QAM_38225_1RB#24




Date: 13.FEB.2019 16:38:56

Band38_5MHz_16QAM_37775_25RB#0




Date: 13.FEB.2019 16:37:09

Band38_5MHz_16QAM_38225_25RB#0




Date: 13.FEB.2019 16:39:44

Band38_10MHz_QPSK_37800_1RB#0




Date: 13.FEB.2019 16:41:04

Band38_10MHz_QPSK_38200_1RB#49




Date: 13.FEB.2019 16:43:17

Band38_10MHz_QPSK_37800_50RB#0




Date: 13.FEB.2019 16:42:00

Band38_10MHz_QPSK_38200_50RB#0




Date: 13.FEB.2019 16:43:51

Band38_10MHz_16QAM_37800_1RB#0




Date: 13.FEB.2019 16:41:34

Band38_10MHz_16QAM_38200_1RB#49




Date: 13.FEB.2019 16:42:52

Band38_10MHz_16QAM_37800_50RB#0




Date: 13.FEB.2019 16:41:51


Band38_10MHz_16QAM_38200_50RB#0




Band38_15MHz_QPSK_37825_1RB#0



Band38_15MHz_QPSK_38175_1RB#74




Band38_15MHz_QPSK_37825_75RB#0




Date: 13.FEB.2019 16:46:12

Band38_15MHz_QPSK_38175_75RB#0




Date: 13.FEB.2019 16:48:07

Band38_15MHz_16QAM_37825_1RB#0




Date: 13.FEB.2019 16:45:09

Band38_15MHz_16QAM_38175_1RB#74




Date: 13.FEB.2019 16:47:05

Band38_15MHz_16QAM_37825_75RB#0




Date: 13.FEB.2019 16:45:56

Band38_15MHz_16QAM_38175_75RB#0




Date: 13.FEB.2019 16:47:47

Band38_20MHz_QPSK_37850_1RB#0




Date: 13.FEB.2019 16:48:58

Band38_20MHz_QPSK_38150_1RB#99




Date: 13.FEB.2019 16:55:47

Band38_20MHz_QPSK_37850_100RB#0




Date: 13.FEB.2019 16:49:50

Band38_20MHz_QPSK_38150_100RB#0




Date: 13.FEB.2019 16:57:07

Band38_20MHz_16QAM_37850_1RB#0




Date: 13.FEB.2019 16:49:24

Band38_20MHz_16QAM_38150_1RB#99




Date: 13.FEB.2019 16:53:53


Band38_20MHz_16QAM_37850_100RB#0



Band38_20MHz_16QAM_38150_100RB#0




Band39_5MHz_QPSK_38275_1RB#0




Date: 14 FEB 2019 16:46:14

Band39_5MHz_QPSK_38525_1RB#24




Date: 14 FEB 2019 16:52:30

Band39_5MHz_QPSK_38275_25RB#0




Date: 14 FEB 2019 18:45:18


Band39_5MHz_QPSK_38525_25RB#0




Band39_5MHz_16QAM_38275_1RB#0



Band39_5MHz_16QAM_38275_1RB#24




Band39_5MHz_16QAM_38275_25RB#0




Date: 14.FEB.2019 16:44:44

Band39_5MHz_16QAM_38525_25RB#0




Date: 14.FEB.2019 16:50:22

Band39_10MHz_QPSK_38300_1RB#0




Date: 14.FEB.2019 16:57:34


Band39_10MHz_QPSK_38500_1RB#49




Band39_10MHz_QPSK_38300_50RB#0



Band39_10MHz_QPSK_38500_50RB#0




Band39_10MHz_16QAM_38300_1RB#0




Date: 14.FEB.2019 16:57:20

Band39_10MHz_16QAM_38500_1RB#49



Date: 14.FEB.2019 19:04:49

Band39_10MHz_16QAM_38300_50RB#0




Date: 14.FEB.2019 18:56:46


Band39_10MHz_16QAM_38500_50RB#0




Band39_15MHz_QPSK_38325_1RB#0



Band39_15MHz_QPSK_38475_1RB#74




Band39_15MHz_QPSK_38325_75RB#0




Date: 14.FEB.2019 19:09:18

Band39_15MHz_QPSK_38475_75RB#0




Date: 14.FEB.2019 19:19:13

Band39_15MHz_16QAM_38325_1RB#0




Date: 14.FEB.2019 19:10:08


Band39_15MHz_16QAM_38475_1RB#74




Band39_15MHz_16QAM_38325_75RB#0



Band39_15MHz_16QAM_38475_75RB#0




Band39_20MHz_QPSK_38350_1RB#0




Date: 14.FEB.2019 19:27:31

Band39_20MHz_QPSK_38450_1RB#99




Date: 14.FEB.2019 19:34:44

Band39_20MHz_QPSK_38350_100RB#0




Date: 14.FEB.2019 19:26:55


Band39_20MHz_QPSK_38450_100RB#0




Band39_20MHz_16QAM_38350_1RB#0




Band39_20MHz_16QAM_38450_1RB#99




Band39_20MHz_16QAM_38350_100RB#0




Band39_20MHz_16QAM_38450_100RB#0




Band41_5MHz_QPSK_40265_1RB#0




Band41_5MHz_QPSK_41265_1RB#24




Band41_5MHz_QPSK_40265_25RB#0




Band41_5MHz_QPSK_41265_25RB#0




Band41_5MHz_16QAM_40265_1RB#0



Band41_5MHz_16QAM_41265_1RB#24




Band41_5MHz_16QAM_40265_25RB#0




Date: 15.FEB.2019 06:10:47

Band41_5MHz_16QAM_41265_25RB#0




Date: 15.FEB.2019 06:17:42

Band41_10MHz_QPSK_40290_1RB#0




Date: 15.FEB.2019 09:28:03


Band41_10MHz_QPSK_41290_1RB#49




Band41_10MHz_QPSK_40290_50RB#0




Band41_10MHz_QPSK_41290_50RB#0




Band41_10MHz_16QAM_40290_1RB#0




Band41_10MHz_16QAM_41290_1RB#49




Band41_10MHz_16QAM_40290_50RB#0



Band41_10MHz_16QAM_41290_50RB#0




Band41_15MHz_QPSK_40315_1RB#0




Band41_15MHz_QPSK_41315_1RB#74




Band41_15MHz_QPSK_40315_75RB#0



Band41_15MHz_QPSK_41315_75RB#0



Band41_15MHz_16QAM_40315_1RB#0




Band41_15MHz_16QAM_41315_1RB#74




Date: 15.FEB.2019 06:48:22

Band41_15MHz_16QAM_40315_75RB#0




Date: 15.FEB.2019 06:40:47

Band41_15MHz_16QAM_41315_75RB#0




Date: 15.FEB.2019 09:49:05


Band41_20MHz_QPSK_40340_1RB#0




Band41_20MHz_QPSK_41140_1RB#99




Band41_20MHz_QPSK_40340_100RB#0




Band41_20MHz_QPSK_41140_100RB#0




Band41_20MHz_16QAM_40340_1RB#0




Band41_20MHz_16QAM_41140_1RB#99



Band41_20MHz_16QAM_40340_100RB#0



Band41_20MHz_16QAM_41140_100RB#0



Conducted Spurious Emission

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Frequency Range	Result (dBm)	Verdict
Band2	1.4MHz	QPSK	18607	6RB#0	Range1:0.009~0.15MHz	-71.46	PASS
Band2	1.4MHz	QPSK	18607	6RB#0	Range2:0.15~30MHz	-47.54	PASS
Band2	1.4MHz	QPSK	18607	6RB#0	Range3:30~1000MHz	-38.3	PASS
Band2	1.4MHz	QPSK	18607	6RB#0	Range4:1000~5000MHz	-41.86	PASS
Band2	1.4MHz	QPSK	18607	6RB#0	Range5:5000~12000MHz	-51.93	PASS
Band2	1.4MHz	QPSK	18607	6RB#0	Range6:12000~18000MHz	-44.07	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	Range1:0.009~0.15MHz	-71.82	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	Range2:0.15~30MHz	-48.57	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	Range3:30~1000MHz	-38.67	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	Range4:1000~5000MHz	-41.75	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	Range5:5000~12000MHz	-51.9	PASS
Band2	1.4MHz	QPSK	18900	6RB#0	Range6:12000~18000MHz	-44.18	PASS
Band2	1.4MHz	QPSK	19193	6RB#0	Range1:0.009~0.15MHz	-72.35	PASS
Band2	1.4MHz	QPSK	19193	6RB#0	Range2:0.15~30MHz	-48.29	PASS
Band2	1.4MHz	QPSK	19193	6RB#0	Range3:30~1000MHz	-38.22	PASS
Band2	1.4MHz	QPSK	19193	6RB#0	Range4:1000~5000MHz	-41.77	PASS
Band2	1.4MHz	QPSK	19193	6RB#0	Range5:5000~12000MHz	-51.92	PASS
Band2	1.4MHz	QPSK	19193	6RB#0	Range6:12000~18000MHz	-44.16	PASS
Band2	1.4MHz	16QAM	18607	6RB#0	Range1:0.009~0.15MHz	-67.57	PASS
Band2	1.4MHz	16QAM	18607	6RB#0	Range2:0.15~30MHz	-49.34	PASS
Band2	1.4MHz	16QAM	18607	6RB#0	Range3:30~1000MHz	-38.13	PASS
Band2	1.4MHz	16QAM	18607	6RB#0	Range4:1000~5000MHz	-41.74	PASS
Band2	1.4MHz	16QAM	18607	6RB#0	Range5:5000~12000MHz	-51.64	PASS
Band2	1.4MHz	16QAM	18607	6RB#0	Range6:12000~18000MHz	-44.09	PASS
Band2	1.4MHz	16QAM	18900	6RB#0	Range1:0.009~0.15MHz	-67.55	PASS
Band2	1.4MHz	16QAM	18900	6RB#0	Range2:0.15~30MHz	-49.59	PASS
Band2	1.4MHz	16QAM	18900	6RB#0	Range3:30~1000MHz	-38.27	PASS
Band2	1.4MHz	16QAM	18900	6RB#0	Range4:1000~5000MHz	-41.68	PASS
Band2	1.4MHz	16QAM	18900	6RB#0	Range5:5000~12000MHz	-51.95	PASS
Band2	1.4MHz	16QAM	18900	6RB#0	Range6:12000~18000MHz	-44.21	PASS
Band2	1.4MHz	16QAM	19193	6RB#0	Range1:0.009~0.15MHz	-67.55	PASS
Band2	1.4MHz	16QAM	19193	6RB#0	Range2:0.15~30MHz	-50.52	PASS