



Band2_10MHz_QPSK_18900_50RB#0




Date: 15.FEB.2019 20:33:50

Band2_10MHz_QPSK_19150_1RB#0




Date: 15.FEB.2019 20:34:05

Band2_10MHz_QPSK_19150_50RB#0




Date: 15.FEB.2019 20:34:17

Band2_10MHz_16QAM_18650_1RB#0




Date: 15.FEB.2019 21:32:01

Band2_10MHz_16QAM_18650_50RB#0




Date: 15.FEB.2019 21:32:13

Band2_10MHz_16QAM_18900_1RB#0




Date: 15.FEB.2019 21:32:28

Band2_10MHz_16QAM_18900_50RB#0




Date: 15.FEB.2019 21:32:40

Band2_10MHz_16QAM_19150_1RB#0




Date: 15.FEB.2019 21:32:55

Band2_10MHz_16QAM_19150_50RB#0




Date: 15.FEB.2019 21:33:07

Band2_15MHz_QPSK_18675_1RB#0




Date: 15.FEB.2019 20:42:53

Band2_15MHz_QPSK_18675_75RB#0




Date: 15.FEB.2019 20:43:05

Band2_15MHz_QPSK_18900_1RB#0




Date: 15.FEB.2019 20:43:20

Band2_15MHz_QPSK_18900_75RB#0




Date: 15.FEB.2019 20:43:32

Band2_15MHz_QPSK_19125_1RB#0




Date: 15.FEB.2019 20:43:47

Band2_15MHz_QPSK_19125_75RB#0




Date: 15.FEB.2019 20:43:59

Band2_15MHz_16QAM_18675_1RB#0




Date: 15.FEB.2019 21:43:25

Band2_15MHz_16QAM_18675_75RB#0




Date: 15.FEB.2019 21:43:37

Band2_15MHz_16QAM_18900_1RB#0




Date: 15.FEB.2019 21:43:53


Band2_15MHz_16QAM_18900_75RB#0




Band2_15MHz_16QAM_19125_1RB#0



Band2_15MHz_16QAM_19125_75RB#0




Band2_20MHz_QPSK_18700_1RB#0




Date: 15.FEB.2019 20:52:40

Band2_20MHz_QPSK_18700_100RB#0




Date: 15.FEB.2019 20:52:52

Band2_20MHz_QPSK_18900_1RB#0




Date: 15.FEB.2019 20:53:08

Band2_20MHz_QPSK_18900_100RB#0




Date: 15.FEB.2019 20:53:20

Band2_20MHz_QPSK_19100_1RB#0




Date: 15.FEB.2019 20:53:35

Band2_20MHz_QPSK_19100_100RB#0




Date: 15.FEB.2019 20:53:47

Band2_20MHz_16QAM_18700_1RB#0




Date: 15.FEB.2019 21:53:26

Band2_20MHz_16QAM_18700_100RB#0




Date: 15.FEB.2019 21:53:38

Band2_20MHz_16QAM_18900_1RB#0




Date: 15.FEB.2019 21:53:54


Band2_20MHz_16QAM_18900_100RB#0




Band2_20MHz_16QAM_19100_1RB#0




Band2_20MHz_16QAM_19100_100RB#0




Band5_1.4MHz_QPSK_20407_1RB#0




Band5_1.4MHz_QPSK_20407_6RB#0




Band5_1.4MHz_QPSK_20525_1RB#0




Band5_1.4MHz_QPSK_20525_6RB#0




Band5_1.4MHz_QPSK_20643_1RB#0



Band5_1.4MHz_QPSK_20643_6RB#0




Band5_1.4MHz_16QAM_20407_1RB#0




Date: 31.DEC.2018 20:49:23

Band5_1.4MHz_16QAM_20407_6RB#0




Date: 31.DEC.2018 20:49:41

Band5_1.4MHz_16QAM_20525_1RB#0




Date: 31.DEC.2018 20:50:02

Band5_1.4MHz_16QAM_20525_6RB#0




Date: 31.DEC.2018 20:50:20

Band5_1.4MHz_16QAM_20643_1RB#0




Date: 31.DEC.2018 20:50:41

Band5_1.4MHz_16QAM_20643_6RB#0




Date: 31.DEC.2018 20:50:59

Band5_3MHz_QPSK_20415_1RB#0




Date: 31.DEC.2018 22:30:31

Band5_3MHz_QPSK_20415_15RB#0




Date: 31.DEC.2018 22:30:48

Band5_3MHz_QPSK_20525_1RB#0




Date: 31.DEC.2018 22:31:10


Band5_3MHz_QPSK_20525_15RB#0




Band5_3MHz_QPSK_20635_1RB#0




Band5_3MHz_QPSK_20635_15RB#0




Band5_3MHz_16QAM_20415_1RB#0




Band5_3MHz_16QAM_20415_15RB#0




Band5_3MHz_16QAM_20525_1RB#0




Band5_3MHz_16QAM_20525_15RB#0




Band5_3MHz_16QAM_20635_1RB#0




Band5_3MHz_16QAM_20635_15RB#0




Band5_5MHz_QPSK_20425_1RB#0




Band5_5MHz_QPSK_20425_25RB#0




Band5_5MHz_QPSK_20525_1RB#0




Band5_5MHz_QPSK_20525_25RB#0




Band5_5MHz_QPSK_20625_1RB#0




Band5_5MHz_QPSK_20625_25RB#0




Band5_5MHz_16QAM_20425_1RB#0




Band5_5MHz_16QAM_20425_25RB#0




Band5_5MHz_16QAM_20525_1RB#0




Band5_5MHz_16QAM_20525_25RB#0




Band5_5MHz_16QAM_20625_1RB#0




Band5_5MHz_16QAM_20625_25RB#0




Band5_10MHz_QPSK_20450_1RB#0




Band5_10MHz_QPSK_20450_50RB#0



Band5_10MHz_QPSK_20525_1RB#0




Band5_10MHz_QPSK_20525_50RB#0




Date: 1.JAN.2019 01:46:41

Band5_10MHz_QPSK_20600_1RB#0




Date: 1.JAN.2019 01:47:03

Band5_10MHz_QPSK_20600_50RB#0




Date: 1.JAN.2019 01:47:21

Band5_10MHz_16QAM_20450_1RB#0




Date: 1.JAN.2019 01:43:22

Band5_10MHz_16QAM_20450_50RB#0




Date: 1.JAN.2019 01:43:40

Band5_10MHz_16QAM_20525_1RB#0




Date: 1.JAN.2019 01:46:32


Band5_10MHz_16QAM_20525_50RB#0




Band5_10MHz_16QAM_20600_1RB#0



Band5_10MHz_16QAM_20600_50RB#0




Band7_5MHz_QPSK_20775_1RB#0




Date: 15.FEB.2019 22:52:34

Band7_5MHz_QPSK_20775_25RB#0




Date: 15.FEB.2019 22:52:58

Band7_5MHz_QPSK_21100_1RB#0




Date: 15.FEB.2019 22:53:25

Band7_5MHz_QPSK_21100_25RB#0




Date: 15.FEB.2019 22:53:49

Band7_5MHz_QPSK_21425_1RB#0




Date: 15.FEB.2019 22:54:17

Band7_5MHz_QPSK_21425_25RB#0




Date: 15.FEB.2019 22:54:41

Band7_5MHz_16QAM_20775_1RB#0




Date: 15.FEB.2019 22:52:46

Band7_5MHz_16QAM_20775_25RB#0




Date: 15.FEB.2019 22:53:10

Band7_5MHz_16QAM_21100_1RB#0




Date: 15.FEB.2019 22:53:37

Band7_5MHz_16QAM_21100_25RB#0




Date: 15.FEB.2019 22:54:01

Band7_5MHz_16QAM_21425_1RB#0




Date: 15.FEB.2019 22:54:29

Band7_5MHz_16QAM_21425_25RB#0




Date: 15.FEB.2019 22:54:53


Band7_10MHz_QPSK_20800_1RB#0




Band7_10MHz_QPSK_20800_50RB#0



Band7_10MHz_QPSK_21100_1RB#0




Band7_10MHz_QPSK_21100_50RB#0




Date: 15.FEB.2019 23:08:53

Band7_10MHz_QPSK_21400_1RB#0




Date: 15.FEB.2019 23:09:21

Band7_10MHz_QPSK_21400_50RB#0




Date: 15.FEB.2019 23:09:45

Band7_10MHz_16QAM_20800_1RB#0




Date: 15.FEB.2019 23:07:49

Band7_10MHz_16QAM_20800_50RB#0




Date: 15.FEB.2019 23:08:13

Band7_10MHz_16QAM_21100_1RB#0




Date: 15.FEB.2019 23:08:41


Band7_10MHz_16QAM_21100_50RB#0




Band7_10MHz_16QAM_21400_1RB#0



Band7_10MHz_16QAM_21400_50RB#0




Band7_15MHz_QPSK_20825_1RB#0




Date: 15.FEB.2019 23:23:25

Band7_15MHz_QPSK_20825_75RB#0




Date: 15.FEB.2019 23:23:48

Band7_15MHz_QPSK_21100_1RB#0




Date: 15.FEB.2019 23:24:16

Band7_15MHz_QPSK_21100_75RB#0




Date: 15.FEB.2019 23:24:40

Band7_15MHz_QPSK_21375_1RB#0




Date: 15.FEB.2019 23:25:08

Band7_15MHz_QPSK_21375_75RB#0




Date: 15.FEB.2019 23:25:32

Band7_15MHz_16QAM_20825_1RB#0




Date: 15.FEB.2019 23:23:36

Band7_15MHz_16QAM_20825_75RB#0




Date: 15.FEB.2019 23:24:00

Band7_15MHz_16QAM_21100_1RB#0




Date: 15.FEB.2019 23:24:28


Band7_15MHz_16QAM_21100_75RB#0




Band7_15MHz_16QAM_21375_1RB#0



Band7_15MHz_16QAM_21375_75RB#0




Band7_20MHz_QPSK_20850_1RB#0




Date: 15.FEB.2019 23:42:19

Band7_20MHz_QPSK_20850_100RB#0




Date: 15.FEB.2019 23:42:43

Band7_20MHz_QPSK_21100_1RB#0




Date: 15.FEB.2019 23:43:11


Band7_20MHz_QPSK_21100_100RB#0




Band7_20MHz_QPSK_21350_1RB#0



Band7_20MHz_QPSK_21350_100RB#0




Band7_20MHz_16QAM_20850_1RB#0




Date: 15.FEB.2019 23:42:31

Band7_20MHz_16QAM_20850_100RB#0




Date: 15.FEB.2019 23:42:56

Band7_20MHz_16QAM_21100_1RB#0




Date: 15.FEB.2019 23:43:23

Band7_20MHz_16QAM_21100_100RB#0




Date: 15.FEB.2019 23:43:47

Band7_20MHz_16QAM_21350_1RB#0




Date: 15.FEB.2019 23:44:15

Band7_20MHz_16QAM_21350_100RB#0




Date: 15.FEB.2019 23:44:39

Band12_1.4MHz_QPSK_23017_1RB#0




Date: 16.FEB.2019 09:52:37

Band12_1.4MHz_QPSK_23017_6RB#0




Date: 16.FEB.2019 09:53:01

Band12_1.4MHz_QPSK_23095_1RB#0




Date: 16.FEB.2019 09:53:32

Band12_1.4MHz_QPSK_23095_6RB#0




Date: 16.FEB.2019 09:53:56

Band12_1.4MHz_QPSK_23173_1RB#0



Date: 16.FEB.2019 09:54:28

Band12_1.4MHz_QPSK_23173_6RB#0



Date: 16.FEB.2019 09:54:52