



Internal photographs of equipment under test (inside enclosure)



Shield removed for photograph



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

MIKROTIK
Model: RB711UA-2HnD
Test #: 110610
Test to: FCC (15.247)
File: IntPho RB711UA2HnD

FCC ID#: TV7RB711UA2HnD
SN: 2D6F01DD3C28
Date: July 27, 2011
Page 1 of 2

Back side of EUT PCB (heat sink in place – No components placed under heat sink)



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

MIKROTIK
Model: RB711UA-2HnD
Test #: 110610
Test to: FCC (15.247)
File: IntPho RB711UA2HnD

FCC ID#: TV7RB711UA2HnD
SN: 2D6F01DD3C28
Date: July 27, 2011
Page 2 of 2