**ROGERS LABS, INC.** 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053

Phone / Fax (913) 837-3214

June 26, 2012

Timco Engineering Inc. 849 NW State Road 45 Newberry, FL 32669

Federal Communications Commission Equipment Approval Services P.O. Box 35815 Pittsburgh, PA 15251-3315

Applicant: Mikrotikls SIA Pernavas 46 Riga, Latvia LV-1009

Equipment: FCC ID: TV7RB751G-2HND

**RE:** Test Report Revision 2

Men:

A type error was discovered in test report and has been corrected. The type error was a heading in a table displaying transmitter functional parameters. Page 4 of the report identifies report revisions and locations. The table located on top of page 22 second column was corrected by replacing reference of Milliwatts with dBm. No data has been altered only heading in table. The revised report has been up loaded to your site for use in correcting the report filed with the application.

Should you require any further information, please contact the undersigned. Thank you for your consideration in this matter.

Sincerely,

Soot DRogers

Scot Rogers Rogers Labs, Inc. Enclosures