

Company: MikroTik

Product Name: hAP ac<sup>2</sup>


Report No.: MIKO65 – Internal Photos

**PHOTOS - INTERNAL**




# 1. Internal Photographs

## 1.1.1. Product - Internal




Module - Bottom Side

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Module - Bottom Side - Cans Removed



Module - Top Side

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Module - Top Side - Heat Sink Removed

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



575 Boulder Court  
Pleasanton, California 94566, USA  
Tel: +1 (925) 462 0304  
Fax: +1 (925) 462 0306  
[www.micomlabs.com](http://www.micomlabs.com)