



HERMON LABORATORIES

January 12, 2006

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated January 11, 2006; NESS Ltd.
FCC ID:TVF-L300-CU-V10, ATCB003087

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The corrected file with additional photos "Internal_photos_16732_CU_rev1" was uploaded on January 12, 2006.
- 2) We confirm that the testing was performed in EUT 3 orthogonal positions. The corrected test report NESRAD_FCC.16732_CU_rev1 was uploaded on January 12, 2006.
- 3) The manufacturer declaration, file "FCC_duty_cycle_declaration_CU" was uploaded on January 12, 2006 via Operational Description folder.
- 4) Corrected User Manual (refer to page 6), file "User_guide_16732_rev1" was uploaded on January 12, 2006.
- 5) File "RF_exposure_16732_CU" was uploaded on January 12, 2006.
- 6) Thank you.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories