



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 5, 2006

RE: FCC ID: TW4-906T_ATCB003697
Attention: Peter Lin

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that page 6 of the report states the antenna port of the device is an SMA connector. Please note that page 20 of the report states the connector is a reverse SMA. Please note that an SMA is a standard connector that is not allowed on part 15 devices unless that device is professionally installed. Please note that the manual does not indicate professional installation of this device. Please clearly identify the antenna connector used in this device and please be consistent through out the report. If the antenna is an SMA and not a reverse SMA, please retest the device using a proper non-standard connector. Alternately, please provide a manual that properly addresses professional installation.
2. Please provide information on the device antenna used during radiated emissions and shown in the external photos.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.