

Response to E06-000025-1 and E06-000025-1 IC

E06-000025-1

1. A revised confidentiality letter has been uploaded.
2. A list of antennas and cable combinations has been uploaded.
3. A revised test report has been uploaded.
4. Conducted emissions was not performed on the antenna port and it is not required by the standard.
5. A description of 15.247(h) has been uploaded.

E06-000025-1 IC

1. A revised application with the Canadian representative has been uploaded.
2. A revised manual has been uploaded.
3. A revised manual has been uploaded.