



Standard Communications PTY. LTD.

A.C.N. 000 346 814 A.B.N 93 000 346 814

Head Office: Locked Bag 2086, North Ryde, NSW 1670, Australia.

T: (02) 9844 6666, **F:** (02) 9844 6600 **W:** www.gme.net.au



8th March, 2006

Ms. Linda Elliott
FCC Application Processing Branch
Office of Engineering and Technology
Federal Communications Commission

Our Ref: ED060308-07

Your Ref: 30450

RE: Application of FCC ID to Equipment & Advice of Amended FCC ID

Dear Linda,

In response to e-mail advice we have taken corrective action and now forwarded a diagram ('*MT401-401FF FCC_ID Placement (Version3).pdf*') showing a valid character format FCC ID and its placement on our 406MHz EPIRB product

Further please accept our advice that we wish to amend the previously requested ID which contained the illegal character '/' to:

FCC ID: TXJMT401-FF

Yours faithfully

Craig Duncan

Project Engineering Manager
Standard Communications Pty Ltd