FCC ID: U2M-SN902
Description of Permissive Change
This report is prepared for FCC class II permissive change. The difference compared with the original report is adding second source adapter.

Report No.: RF110516C08B