



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 1, 2007

RE: Double Horse Toys Industry Co., LTD

FCC ID: U2N-GC887849

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) I do not see your 15.21 "Information to User" statements within the Manual. If I have missed it, my apologies. Kindly indicate where I can find it.
- 2.) FYI: Your Block Diagram is a little weak on its explanation of how the circuitry works. However, the Schematics are simple enough that I can derive all the information I need. For the future, please consider strengthening the content within the Block Diagram.
- 3.) Your Operational Description appears to indicate that the helicopter/receiver associated with this transmitter operates on superregenerative ("ultraregenerative") principals. If so, then please be advised that 15.101 requires that all superregenerative receivers follow either Certification or DofC for equipment authorization. If Certification is desired, the receiver must have its own unique FCC ID, and follow the testing procedures of ANSI C63.4 section 12.1.1.1.
- 4.) FYI: I have never encountered the manufacturer listed for your loop antenna before. Can you kindly provide for me the specifications and calibration factors/calibration certificate for this transducer?

William H. Graff
President

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.