

**CONTINENTAL CONAIR LIMITED**

35/F., STANDARD CHARTERED TOWER, MILLENNIUM CITY 1,
388 KWUN TONG ROAD, KWUN TONG, KOWLOON, HONG KONG
TEL. : (852)2751 4688 FAX : (852)2751 8920

Date:2014-6-24

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

Subject: FCC Class II Permission change for FCC ID: U43ICT200

Original Grant Date: 01/12/2012

Dear Sir/Madam,

This is to request a Class II permission change to our Induction cooktop, Model ICT200 (FCC ID: U43ICT200), the device is identical to the previously certified except for the changes as below for details;

Part	Original	New
MAIN PCB	YLS-EE PCB	EG PCB
	without sheet-contact process	sheet-contact process
	MKP-X2 at C16 site	MKP-X2 at C4 site
	Chokes at L3 site	Chokes at L2 site
Control PCB	Control winding is 4 needles	Control winding is 6 needles
Thermal Fuse	without Thermal Fuse	Added Thermal Fuse

Sincerely Yours,

Typed or Printed Name: Leo Leung

Title: Engineering Director-Kitchen Appliance Dept