

18.11.2008

Federal Communication Commission Equipment Authorization Devision, Application Processing Branch 7435 Oakland Mills Road Columbia, MD 21048

Certification and Engineering Bureau Industry Canada Spectrum Engineering Branch 3701 Carling Avenue, Building 94 Ottawa, Ontario K2H 8S2 LANCOM Systems GmbH Adenauerstraße 20 / B2 S2146 Würselen Deutschland Telefon +49 (0)2405 49936-0 Telefax +49 (0)2405 49936-99 www.lancom.de

## **Declaration on Electrically Identical Models**

TO WHOM IT MAY CONCERN

We, LANCOM Sytems GmbH, declare on our sole responsibility that the new model

LANCOM XAC-40-1 with FCC ID: U4Y-SE111 and IC: 7049A-SE111

is identical in hardware and software to the certified model

LANCOM XAP-40-2 under FCC ID: U4Y-SE1I2 and IC: 7049A-SE1I2

The only differences between the new model and the original model are:

- Model LANCOM XAP-40-2 is equipped with two WLAN cards. Model LANCOM XAC-40-1 is equipped with one WLAN card only
- Model LANCOM XAC-40-1 is equipped with alternate front cover

We attest that above changing are not relevant for any RF behaviour subject to regulatory items. Additional Spurious Emissions measurements on representative configurations have been performed to justify.

Therefore all test reports remains applicable.

If you have any questions, please feel free to contact us at the address shown below

Sincerely,

Name:

André Krautschick

Company:

LANCOM Systems GmbH

Address:

Adenauerstr. 20/B2

Phone:

52146 Wuerselen / Germany

T '1

+49 02405 49936 443

Email:

andre.krautschick@lancom.de