


Carestream Health
DV 6950 RFID

FRN 0016195265



Antenna installed under
cover.

RF cable to MCS
circuit board.

DV 6950 Media Drawer with
antenna installed and RF cable
connected.
Before installation in DV 6950.