

## CS5111TD FCC Label





CS5111TD  
RTLS SLAVE ANCHOR NARROW BEAM

IC: 8073A-CS51113TDCA

S/N: V8010D1ES0020

ID No.: 66A20E39E0F1




FCC ID: UB4CS51113TD

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference and (2) this device must accept any interference received, including interference that may cause undesired operation.

Made in China

Ex-factory Firmware  
Version: V78



## CS5112TD FCC Label





CS5112TD  
RTLS SLAVE ANCHOR WIDE BEAM

IC: 8073A-CS51113TDCA

S/N: V8010D1ES0020

ID No.: 66A20E39E0F1


FCC ID: UB4CS51113TD

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference and (2) this device must accept any interference received, including interference that may cause undesired operation.

Made in China


Ex-factory Firmware  
Version: V78

Actual Center  
of Antenna  
to be  
aligned  
Normal  
Vector of surface



CS5113TD FCC Label


45.00

 **CONVERGENCE  
SYSTEMS LIMITED**

CS5113TD


RTLS MASTER ANCHOR  
NARROW BEAM


IC: 8073A-CS5113TDCA


 **FCC ID: UB4CS5113TD**

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:(1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Made In China

  
S/N: V8210D1ES0001

  
ID No.: 66A20E39E0F1

  
MAC Addr.: 000B3C055EEC

Ex-Factory IP: 192.168.25.111

Ex-Factory Target PC Server IP:  
192.168.25.222

80.00



CONVERGENCE  
SYSTEMS LIMITED

CS5113TD  
RTLS MASTER ANCHOR  
NARROW BEAM  
IC: 8073A-CS5113TDCA



FCC ID: UB4CS5113TD

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Made in China

S/N: V8210D1ES0001

ID No.: 86A20E39E0F-1

MAC Addr.: 000B3C055EEC

Ex-Factory IP: 192.168.25.111  
Ex-Factory Target PC Server IP:  
192.168.25.222

Actual Center  
of Antenna  
Beam  
Coincides with  
Normal Vector of surface



Ex-factory Firmware  
Version: V78

CS5114TD FCC Label

45.00

**CONVERGENCE  
SYSTEMS LIMITED**

CS5114TD  
RTLS MASTER ANCHOR  
WIDE BEAM  
IC: 8073A-CS51113TDCA

 **FCC ID: UB4CS51113TD**

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:(1) this device may not cause harmful interference,and (2) this device must accept any interference received, including interference that may cause undesired operation.

Made in China

  
S/N: V8210D1ES0001

  
ID No.: 66A20E39E0F1

  
MAC Addr.: 000B3C055EEC

Ex-Factory IP: 192.168.25.111  
Ex-Factory Target PC Server IP:  
192.168.25.222

80.00



CS5114TD  
RTLS MASTER ANCHOR  
WIDE BEAM  
IC: 8073A-CSS1113TDCA



FCC ID: UB4C551113TD

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference and (2) this device must accept any interference received, including interference that may cause undesired operation.


Made in China

S/N: V8210D1E50001

ID No.: 86A20E38E0F1

MAC Addr.: 000B3C08E0EC

Ex-Factory IP: 192.168.25.113  
Ex-Factory Target IP: 192.168.25.222



Ex-factory Firmware  
Version: V78



## CS5116TD FCC Label





CSL CONVERGENCE  
SYSTEMS LIMITED

CS5116TD  
RTLS SLAVE ANCHOR OMNIDIRECTIONAL BEAM

IC 8073A CS5113TDCA

FCC ID: UB4CS5113TD

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.


S/N: V8010D1E50020

ID No: 68A20E39E0F1

Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Made in China

CS5118TD FCC Label





CSL CONVERGENCE  
SYSTEMS LIMITED

CS5118TD  
RTLS MASTER ANCHOR  
OMNIDIRECTIONAL BEAM  
IC: 8073A-CS51113TDCA

FCC ID: UB4CS51113TD

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Made in China

S/N: V8210D1ES0001

ID No.: 66A20E39E0F1

MAC Addr: 000B3C055EEC

Ex-Factory IP: 192.168.25.111

Ex-Factory Target PC Server IP:

192.168.25.222