



Arcom Control Systems Inc., 7500 West 161st Street Overland Park, Kansas, USA
Telephone (913) 549-1000 Fax (913) 549-1001

December 11, 2006

Re: FCC Change of Identification

To Whom It May Concern:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by Arcom Control Systems will establish a new FCC ID under Arcom Control Systems grantee code for purposes of marketing. The original grant to Sony Ericsson Mobile Communications AB, FCC ID: PY7BC051021 will remain in effect.

Per 2.933(b)

1. The original identification is FCC ID: PY7BC051021
2. The original grant date is May 22, 2006.
3. The equipment is electrically identical and operated without change to the original equipment. Only the model name, trade name, application, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

Sincerely,

A handwritten signature in black ink that reads "Jon Tandy". The signature is fluid and cursive, with a long horizontal stroke at the end.

Jon Tandy
Project Engineer
Arcom Control Systems, Inc.