

Scott McCutchan

From: Scott McCutchan [scott@celectronics.com]
Sent: Thursday, May 27, 2010 7:18 PM
To: 'kyle@celectronics.com'
Cc: 'mike@celectronics.com'; 'jeff@celectronics.com'
Subject: FCC ID: UGP-WSW001

Mr. Fujimoto:

In order for processing of this certification application (FCC ID: UGP-WSW001) to continue, the following issue(s) will have to be addressed:

- 1) The two-condition statement contained in section 15.31(a)(3) of the FCC rules does not appear on the device label. Per section 15.31(a)(5), when the device is so small that it is not practicable to put this statement on the device, it can alternatively be placed in the instruction manual. Please submit either a revised label, or a revised user's manual, with the statement included.
- 2) The schematic diagrams submitted are incomplete. Please submit the full set of schematics
- 3) The FCC ID printed on the example label is "UGP-W5W001", which does not match the FCC ID on the rest of the application. Please correct the label, or if the label is correct, please submit the application with the correct identifier.
- 4) Based on the submitted duty cycle plots, the on-time used for the duty cycle calculation is incorrect. Please correct.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Please upload responses and/or exhibits to the electronic filing website. Your correspondence number is FCC ID: UGP-WSW001-1.

Best regards,

Scott McCutchan
Operations Manager
Compatible Electronics TCB