## TEST SETUP PHOTOGRAPHS

1. AC input power measurement



2. Conducted Emission Test



3. Operation frequency measurement



4. Radiated emission measurement



## 5. Radiation hazard test



6. RF output power measurement

