

10. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




RADIATED RF MEASUREMENT SETUP - EUT WITH AC ADAPTER ONLY

Front




Back




RADIATED RF MEASUREMENT SETUP - EUT WITH CRADLE CHARGER AND AC ADAPTER

Front



Back



POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP

EUT WITH AC ADAPTER ONLY

Front



EUT WITH CRADLE CHARGER AND AC ADAPTER



END OF REPORT