

Twynam, Tom

From: Zhang, Changxin
Sent: 21 October 2009 06:10
To: Twynam, Tom
Subject: Inventec FCC SAR report
Attachments: UPMW310001_SAR Test Report_Rev.pdf

Importance: High
Sensitivity: Confidential

Dear Tom,

They give some updates as following, please help to deal with:

1. It appears all SAR scan regions Please review and correct if applicable. Please review the device configuration and position holder to provide SAR measurement.

[The relative revise has been made. Please refer to the test report Page 27 of 54 to page 37 of 54.](#)

2. Provide detailed in the Probe Calibration procedures and show that System Verification Application Note (AP) are followed and specific items/issued identified in the AP are Properly addressed in the test report. 3. Which calibration point is used for the SAR measurements?

[The detailed information of calibration issue is provided. Please refer to the test report page 22 of 54 and page 24 of 54.](#)

4. SAR measurement: need further clarification on what was tested; these appear to some Incorrect measurements?

[The further clarification and information about the tests are provided. Please refer to the test report page 5 of 54 and page 17 of 54 for details.](#)

Many thanks.
Regards

Andy