



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

September 10, 2007

RE: ATCB005402

IC ID: UQ5BBKBT

I have a few comments on this application. Depending on your responses, kindly understand there may be additional comments.

1. I could not see the EUT clearly on the turn-table in your provided setup photo. And the power supply is not allowed to put on the turn-table for radiated emission test since it would vary the measured results for the radiation emission, which is required to be placed on the ground plane below the turn-table.

Please provide the revised setup photos with correct setup and the EUT seen clearly on the turn-table.

---

~~~~~  
~ George Chen  
~ [mailto:george@atcb.com](mailto:mailto:george@atcb.com)  
~ Taiwan Mobile: +886 930600123  
~ SKYPE: georgeshirley

---

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.