Declaration

Date: 13 January 2010

Subject: FCC Application FCC ID: UZ7MC3190

The device, Mobile Computer, Model: MC3190 has below conditions which may cause SAR value lower. Please refer to below table:

	Original Fabric Holster	New Belt Clip
Materials	Fabric	Plastic
Gaps with Body	More Shorter	More Longer
Max. Body SAR	0.55	0.091

The SAR results for above conditions could refer to previous and current RF Exposure reports for reference. The new belt clip will have additional marketing purpose and original fabric holsters are remained. Therefore, the SAR values on the grant could be kept original version because the SAR of fabric holster is higher than new belt clip which will not be replaced from original version.

In other words, not only original fabric holsters but also new belt clip will be sold and SAR results could be shown in current reports.

Sincerely Yours,

Roy Wu / Manager

Sporton International Inc.

Tel: 886-3-327-3456 Ext. 604

Fax: 886-3-328-4978

Email: Roy@sporton.com.tw

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : 1 of 1