



APPENDIX I SETUP PHOTOS

RADIATED EMISSION SETUP

Below 1 GHz

Mode 1







Mode 2








Mode 3-Charge





Mode 3-Power Adapter







Mode 4-Charge







Mode 4-Power Adapter





Mode 5








Above 1 GHz





ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





CONDUCTED EMISSION SETUP

Mode 3-Charge





Mode 3-Powr Adapter





Mode 4-Charge





Mode 4-Powr Adapter





Mode 5

