



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 1.SEP.2022 15:38:26

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 1.SEP.2022 15:38:45

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 1.SEP.2022 15:39:04

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 1.SEP.2022 15:39:22

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 1.SEP.2022 15:39:41

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 1.SEP.2022 15:39:58

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 1.SEP.2022 15:40:58

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 1.SEP.2022 15:41:13

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 1.SEP.2022 15:41:29

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 1.SEP.2022 15:41:44

Band 2_3 MHz_High_QPSK_RB15#0




Date: 1.SEP.2022 15:41:59

Band 2_3 MHz_High_16QAM_RB15#0




Date: 1.SEP.2022 15:42:17

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 1.SEP.2022 15:44:37

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 1.SEP.2022 15:44:56

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 1.SEP.2022 15:45:12

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 1.SEP.2022 15:45:31

Band 2_5 MHz_High_QPSK_RB25#0




Date: 1.SEP.2022 15:45:50

Band 2_5 MHz_High_16QAM_RB25#0




Date: 1.SEP.2022 15:46:10

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 1.SEP.2022 15:47:42

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 1.SEP.2022 15:48:02

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 1.SEP.2022 15:48:20

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 1.SEP.2022 15:48:39

Band 2_10 MHz_High_QPSK_RB50#0




Date: 1.SEP.2022 15:48:56

Band 2_10 MHz_High_16QAM_RB50#0




Date: 1.SEP.2022 15:49:15

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 1.SEP.2022 15:50:02

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 1.SEP.2022 15:50:21

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 1.SEP.2022 15:50:40

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 1.SEP.2022 15:50:59

Band 2_15 MHz_High_QPSK_RB75#0




Date: 1.SEP.2022 15:51:22

Band 2_15 MHz_High_16QAM_RB75#0




Date: 1.SEP.2022 15:51:44

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 1.SEP.2022 15:52:30

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 1.SEP.2022 15:52:53

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 1.SEP.2022 15:53:13

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 1.SEP.2022 15:53:35

Band 2_20 MHz_High_QPSK_RB100#0




Date: 1.SEP.2022 15:53:56

Band 2_20 MHz_High_16QAM_RB100#0




Date: 1.SEP.2022 15:54:15

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 1.SEP.2022 15:54:36

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 1.SEP.2022 15:54:51

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 1.SEP.2022 15:55:07

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 1.SEP.2022 15:55:25

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 1.SEP.2022 15:55:44

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 1.SEP.2022 15:56:02

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 1.SEP.2022 15:57:57

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 1.SEP.2022 15:58:13

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 1.SEP.2022 15:58:29

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 1.SEP.2022 15:58:44

Band 4_3 MHz_High_QPSK_RB15#0




Date: 1.SEP.2022 15:59:00

Band 4_3 MHz_High_16QAM_RB15#0




Date: 1.SEP.2022 15:59:15

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 1.SEP.2022 16:00:19

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 1.SEP.2022 16:00:34

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 1.SEP.2022 16:00:54

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 1.SEP.2022 16:01:09

Band 4_5 MHz_High_QPSK_RB25#0




Date: 1.SEP.2022 16:01:32

Band 4_5 MHz_High_16QAM_RB25#0




Date: 1.SEP.2022 16:01:51

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 1.SEP.2022 16:02:55

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 1.SEP.2022 16:03:14

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 1.SEP.2022 16:03:34

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 1.SEP.2022 16:03:53

Band 4_10 MHz_High_QPSK_RB50#0




Date: 1.SEP.2022 16:04:14

Band 4_10 MHz_High_16QAM_RB50#0




Date: 1.SEP.2022 16:04:33

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 1.SEP.2022 16:05:46

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 1.SEP.2022 16:06:05

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 1.SEP.2022 16:06:25

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 1.SEP.2022 16:06:47

Band 4_15 MHz_High_QPSK_RB75#0




Date: 1.SEP.2022 16:07:10

Band 4_15 MHz_High_16QAM_RB75#0




Date: 1.SEP.2022 16:07:32

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 1.SEP.2022 16:08:40

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 1.SEP.2022 16:08:59

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 1.SEP.2022 16:09:23

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 1.SEP.2022 16:09:45

Band 4_20 MHz_High_QPSK_RB100#0




Date: 1.SEP.2022 16:10:08

Band 4_20 MHz_High_16QAM_RB100#0




Date: 1.SEP.2022 16:10:27

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 1.SEP.2022 16:11:16

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 1.SEP.2022 16:11:31

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 1.SEP.2022 16:11:50

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 1.SEP.2022 16:12:08

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 1.SEP.2022 16:12:24

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 1.SEP.2022 16:12:42

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 1.SEP.2022 16:18:04

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 1.SEP.2022 16:18:19

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 1.SEP.2022 16:18:35

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 1.SEP.2022 16:18:50

Band 5_3 MHz_High_QPSK_RB15#0




Date: 1.SEP.2022 16:19:06

Band 5_3 MHz_High_16QAM_RB15#0




Date: 1.SEP.2022 16:19:21

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 1.SEP.2022 16:20:17

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 1.SEP.2022 16:20:35

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 1.SEP.2022 16:21:01

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 1.SEP.2022 16:21:20

Band 5_5 MHz_High_QPSK_RB25#0




Date: 1.SEP.2022 16:21:46

Band 5_5 MHz_High_16QAM_RB25#0




Date: 1.SEP.2022 16:22:01

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 1.SEP.2022 16:23:21

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 1.SEP.2022 16:23:40

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 1.SEP.2022 16:24:00

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 1.SEP.2022 16:24:20

Band 5_10 MHz_High_QPSK_RB50#0




Date: 1.SEP.2022 16:24:40

Band 5_10 MHz_High_16QAM_RB50#0




Date: 1.SEP.2022 16:24:59

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 1.SEP.2022 16:25:23

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 1.SEP.2022 16:25:38

Band 12_1.4 MHz_Middle_QPSK_RB6#0




Date: 1.SEP.2022 16:25:54

Band 12_1.4 MHz_Middle_16QAM_RB6#0




Date: 1.SEP.2022 16:26:09

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 1.SEP.2022 16:26:28

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 1.SEP.2022 16:26:42

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 1.SEP.2022 16:28:46

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 1.SEP.2022 16:29:04

Band 12_3 MHz_Middle_QPSK_RB15#0




Date: 1.SEP.2022 16:29:23

Band 12_3 MHz_Middle_16QAM_RB15#0




Date: 1.SEP.2022 16:29:41

Band 12_3 MHz_High_QPSK_RB15#0




Date: 1.SEP.2022 16:29:57

Band 12_3 MHz_High_16QAM_RB15#0




Date: 1.SEP.2022 16:30:12

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 1.SEP.2022 16:31:37

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 1.SEP.2022 16:31:55

Band 12_5 MHz_Middle_QPSK_RB25#0




Date: 1.SEP.2022 16:32:15

Band 12_5 MHz_Middle_16QAM_RB25#0




Date: 1.SEP.2022 16:32:37

Band 12_5 MHz_High_QPSK_RB25#0




Date: 1.SEP.2022 16:32:53

Band 12_5 MHz_High_16QAM_RB25#0




Date: 1.SEP.2022 16:33:09

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 1.SEP.2022 16:34:22

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 1.SEP.2022 16:34:41

Band 12_10 MHz_Middle_QPSK_RB50#0




Date: 1.SEP.2022 16:35:02

Band 12_10 MHz_Middle_16QAM_RB50#0




Date: 1.SEP.2022 16:35:21

Band 12_10 MHz_High_QPSK_RB50#0




Date: 1.SEP.2022 16:35:41

Band 12_10 MHz_High_16QAM_RB50#0




Date: 1.SEP.2022 16:35:57

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 8.SEP.2022 15:48:11

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 8.SEP.2022 15:48:29

Band 38_5 MHz_Middle_QPSK_RB25#0




Date: 8.SEP.2022 15:48:51

Band 38_5 MHz_Middle_16QAM_RB25#0




Date: 8.SEP.2022 15:49:05

Band 38_5 MHz_High_QPSK_RB25#0




Date: 8.SEP.2022 15:49:21

Band 38_5 MHz_High_16QAM_RB25#0




Date: 8.SEP.2022 15:49:42

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 8.SEP.2022 16:00:47

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 8.SEP.2022 16:01:06

Band 38_10 MHz_Middle_QPSK_RB50#0




Date: 8.SEP.2022 16:01:25

Band 38_10 MHz_Middle_16QAM_RB50#0




Date: 8.SEP.2022 16:01:40

Band 38_10 MHz_High_QPSK_RB50#0




Date: 8.SEP.2022 16:01:59

Band 38_10 MHz_High_16QAM_RB50#0




Date: 8.SEP.2022 16:02:18

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 8.SEP.2022 16:04:28

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 8.SEP.2022 16:04:49

Band 38_15 MHz_Middle_QPSK_RB75#0




Date: 8.SEP.2022 16:05:14

Band 38_15 MHz_Middle_16QAM_RB75#0




Date: 8.SEP.2022 16:05:43

Band 38_15 MHz_High_QPSK_RB75#0




Date: 8.SEP.2022 16:06:08

Band 38_15 MHz_High_16QAM_RB75#0




Date: 8.SEP.2022 16:17:54

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 8.SEP.2022 16:19:09

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 8.SEP.2022 16:19:30

Band 38_20 MHz_Middle_QPSK_RB100#0




Date: 8.SEP.2022 16:19:53

Band 38_20 MHz_Middle_16QAM_RB100#0




Date: 8.SEP.2022 16:20:14

Band 38_20 MHz_High_QPSK_RB100#0




Date: 8.SEP.2022 16:20:38

Band 38_20 MHz_High_16QAM_RB100#0




Date: 8.SEP.2022 16:21:02

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 8.SEP.2022 16:31:58

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 8.SEP.2022 16:32:20

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 8.SEP.2022 16:32:41

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 8.SEP.2022 16:32:56

Band 41_5 MHz_High_QPSK_RB25#0




Date: 8.SEP.2022 16:33:15

Band 41_5 MHz_High_16QAM_RB25#0




Date: 8.SEP.2022 16:33:32

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 8.SEP.2022 16:34:52

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 8.SEP.2022 16:35:10

Band 41_10 MHz_Middle_QPSK_RB50#0




Date: 8.SEP.2022 16:35:30

Band 41_10 MHz_Middle_16QAM_RB50#0




Date: 8.SEP.2022 16:35:51

Band 41_10 MHz_High_QPSK_RB50#0




Date: 8.SEP.2022 16:36:10

Band 41_10 MHz_High_16QAM_RB50#0




Date: 8.SEP.2022 16:36:25

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 8.SEP.2022 16:56:38

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 8.SEP.2022 16:56:59

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 8.SEP.2022 16:57:24

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 8.SEP.2022 16:57:45

Band 41_15 MHz_High_QPSK_RB75#0




Date: 8.SEP.2022 16:58:07

Band 41_15 MHz_High_16QAM_RB75#0




Date: 8.SEP.2022 16:58:28

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 8.SEP.2022 17:12:33

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 8.SEP.2022 17:12:58

Band 41_20 MHz_Middle_QPSK_RB100#0




Date: 8.SEP.2022 17:13:20

Band 41_20 MHz_Middle_16QAM_RB100#0




Date: 8.SEP.2022 17:13:41

Band 41_20 MHz_High_QPSK_RB100#0



Date: 8.SEP.2022 17:14:04

Band 41_20 MHz_High_16QAM_RB100#0



Date: 8.SEP.2022 17:14:25