



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:29:29

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:29:44

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:30:01

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:30:12

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:30:25

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:30:36

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:31:14

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:31:25

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:31:38

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:31:49

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:32:06

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:32:17

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:32:57

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:33:08

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:33:22

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:33:33

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:33:47

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:33:58

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:34:35

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:34:46

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:35:03

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:35:14

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:35:28

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:35:39

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:36:17

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:36:28

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:36:46

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:36:57

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:37:15

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:37:26

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:38:04

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:38:15

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:38:29

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:38:40

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 1.SEP.2022 17:38:58

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 1.SEP.2022 17:39:09

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:40:03

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:40:14

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:40:27

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:40:38

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:40:55

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:41:06

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:42:09

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:42:20

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:42:33

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:42:44

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:42:58

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:43:09

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:47:13

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:47:24

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:47:38

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:47:49

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:48:05

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:48:16

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:49:21

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:49:32

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:49:49

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:50:00

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:50:14

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:50:25

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:51:23

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:51:34

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:51:49

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:52:00

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:52:17

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:52:28

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:53:33

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:53:44

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:54:02

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:54:13

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:54:31

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 1.SEP.2022 19:54:42

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:55:20

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 1.SEP.2022 19:55:30

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:55:44

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 1.SEP.2022 19:55:55

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:56:11

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 1.SEP.2022 19:56:25

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:57:05

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 1.SEP.2022 19:57:16

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:57:32

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 1.SEP.2022 19:57:43

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 1.SEP.2022 19:57:57

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 1.SEP.2022 19:58:08

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.SEP.2022 20:21:59

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 1.SEP.2022 20:22:10

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.SEP.2022 20:42:42

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 1.SEP.2022 20:42:53

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 1.SEP.2022 20:44:29

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 1.SEP.2022 20:44:40

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:52:19

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:54:14

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:51:04

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:54:45

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:53:13

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:53:50

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:30:14

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:30:24

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:30:40

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:30:50

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:31:03

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:31:13

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:35:34

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:35:45

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:35:58

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:36:08

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:36:21

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:36:34

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:37:43

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:37:53

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:38:06

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:38:17

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:38:30

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:38:40

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:45:08

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:45:19

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:45:36

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:45:46

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 09:46:00

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 8.SEP.2022 09:46:10

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:23:27

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:23:37

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:23:51

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:24:01

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:24:17

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:24:28

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:25:30

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:25:41

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:25:54

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:26:05

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:26:18

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:26:29

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:27:30

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:27:40

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:27:59

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:28:10

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:28:29

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:28:39

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:30:49

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:31:00

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:31:16

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:31:26

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:31:45

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:31:56

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:32:15

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:32:25

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:32:42

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:32:52

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:33:05

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:33:16

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:34:20

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:34:31

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:34:44

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:34:55

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:35:12

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:35:22

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:36:24

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:36:35

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:36:51

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:37:01

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:37:17

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:37:28

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:38:32

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:38:42

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 8.SEP.2022 17:38:59

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 8.SEP.2022 17:39:09

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 8.SEP.2022 17:39:25

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 8.SEP.2022 17:39:35