


8. SETUP PHOTOS

RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION




Y-AXIS PHOTO




Z-AXIS PHOTO




X-AXIS WITH AC ADAPTER PHOTO




X-AXIS WITH AC ADAPTER AND HEADSET PHOTO



Z-AXIS WITH AC ADAPTER PHOTO



Z-AXIS WITH AC ADAPTER AND HEADSET PHOTO



END OF REPORT