

Daviscomms (S) Pte Ltd

Blk 70 Ubi Crescent #01-07, Ubi Techpark 408570 Singapore

Date: Jan. 06, 2017

From: Daviscomms (S) Pte Ltd,
Blk 70 Ubi Crescent #01-07,
Ubi Techpark 408570
Singapore

To: FCC
C.C SIEMIC, INC.
775 Montague Expressway,
Milpitas, CA 95035
USA

RE: Supersede Request Letter

FCC ID: [VDQ828-02](#)

We would like to update BOM, internal photo and SAR report.

1. Because the documents mistake, we submit error files.
2. The equipment code type error of SAR report.


We request to supersede below exhibits due to equipment class change and module photo change mentioned above.

- (1) BOM
- (2) internal photo
- (3) SAR report

Pls kindly let us know if you have any question.

Sincerely,

Client's signature :



Signature:

Name / Title: [Ramasamy Lakshmanan/ Engineer](#)

Contact information / address: [Blk 70 Ubi Crescent #01-07, Ubi Techpark, Singapore](#)