



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

RE: FCCID VFIBW95119805

Attention: Cherry Li

During the review of this device, the following item needs to be clarified. Please be aware that there may be additional questions based upon the response to this item.

- 1) On page 11 of the test report VFIBW95119805 Test Report-Rev1.pdf, the channel 37 30MHz~1GHz table needs to be corrected.

Best Regards,

Michael Mobley
mmobley@atcb.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to the correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.