



# Label



|   |   |   |
|---|---|---|
| <p><b>Midea</b><br/><b>MODEL: TC042A2GM-S(GE)</b><br/>HOUSEHOLD MICROWAVE OVEN<br/>(NOT FOR COMMERCIAL USE)<br/>INPUT 120V~60Hz, SINGLE PHASE 1600W<br/>OUTPUT 1000W, Grill 1300W 2450MHz<br/>MANUFACTURE DATE:<br/>FCC ID:VG8XC042AYYGW<br/>Contains FCC ID:ZKJ-WCATB002<br/>MADE IN SHUNDE CHINA<br/>MIDEA MICROWAVE AND ELECTRICAL<br/>APPLIANCES MANUFACTURING CO LTD<br/>THIS DEVICE COMPLIES WITH DHHS<br/>RADIATION PERFORMANCE<br/>STANDARDS 21 CFR SUBCHAPTER J.</p> |  | <p><b>CAUTION</b> - THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.</p> <p><b>WARNING</b> - TO ENSURE CONTINUED PROTECTION AGAINST ELECTRICAL SHOCK HAZARD, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY. DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTER CASE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS.</p> <ul style="list-style-type: none"><li>• CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL -DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: IF PROVIDED FAN MOTOR, TURNTABLE MOTOR, DAMPER MOTOR, L.V. TRANSFORMER (TOUCH CONTROL TYPE) OR TIMER MOTOR ASSEMBLY (MECHANICAL TYPE).</li><li>• RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.</li><li>• NOT FOR BUILT-IN INSTALLATION.</li></ul> |
|---|---|---|

Size:160\*80mm

Silver-backed black word on the film UL high temperature resistant PGDQ2 material