

Midea

MICROWAVE OVEN

MODEL: EM0P042SU-PS0A00

POWER SUPPLY:120V~ 60Hz

RATED INPUT(MICROWAVE):1600W

RATED OUTPUT(MICROWAVE):1000W

MICROWAVE OUTPUT FREQUENCY:2450MHZ

MANUFACTURE DATE:MM.YYYY

FCC ID:VG8XM0P04YYW

CONTAIN FCC ID:2AC7Z-ESP32PICOZERO

HOUSEHOLD USE ONLY

(NOT FOR COMMERCIAL USE)

THIS DEVICE COMPLIES WITH DHHS

RADIATION PERFORMANCE

STANDARDS 21 CFR SUBCHAPTER J.

MADE IN CHINA

Guangdong Midea Kitchen Appliances

Manufacturing Co.,Ltd.

No.6,Yong An Road,Beijiao,Shunde,Foshan,

Guangdong,China.



WARNING:Cancer and Reproductive
Harm-www.p65warnings.ca.gov



LISTED
54NJ

E214180

CAUTION·THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.

WARNING· TO ENSURE CONTINUED PROTECTION AGAINST ELECTRICAL SHOCK HAZARD, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY.DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTER CASE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS.

· CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING.SERVICE PERSONNEL -DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: IF PROVIDED FAN MOTOR, TURNABLE MOTOR, DAMPER MOTOR,L.V.TRANSFORMER (TOUCH CONTROL TYPE) OR TIMER MOTOR ASSEMBLY (MECHANICAL TYPE).

· RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.

· NOT FOR BUILT-IN INSTALLATION.

Label Location Information

