




认证标志, 不同认证机构的不一样  
需要按实际认证标志替换

The certification mark varies among different certification bodies.  
Need to replace according to the actual certification mark

 MICROWAVE OVEN MODEL: EM262A2SR-P POWER SUPPLY:120 VAC~ 60 Hz RATED INPUT(MICROWAVE):1700 W RATED OUTPUT(MICROWAVE):1200W MICROWAVE OUTPUT FREQUENCY:2450 MHz MANUFACTURE DATE:MM.YYYY FCC ID: VG8XM262AYY2M392 COMMERCIAL USE THIS DEVICE COMPLIES WITH DHHS RADIATION PERFORMANCE STANDARDS 21 CFR SUBCHAPTER J. MADE IN CHINA Guangdong Midea Kitchen Appliances Manufacturing Co.,Ltd. No.6,Yong An Road,Beijiao,Shunde,Foshan, Guangdong,China		<b>CAUTION</b> - THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY. <b>WARNING</b> - TO ENSURE CONTINUED PROTECTION AGAINST ELECTRICAL SHOCK HAZARD, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY. DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTER CASE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS. - CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL -DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: IF PROVIDED FAN MOTOR, TURNABLE MOTOR, DAMPER MOTOR,L.V.TRANSFORMER (TOUCH CONTROL TYPE) OR TIMER MOTOR ASSEMBLY (MECHANICAL TYPE). - RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS. - NOT FOR BUILT-IN INSTALLATION. <b>CAUTION - Hot</b>
 <b>WARNING:</b> Cancer and Reproductive Harm- <a href="http://www.p65warnings.ca.gov">www.p65warnings.ca.gov</a>		

日期号: MM.YYYY

Date Number

规则: 英文月份全称+年份4位

Rule: Full English month name+4-digit year

### FCC ID Label Location Information

