



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

September 14, 2007

RE: Seiden Electric Engineering Co., Ltd

FCC ID: VGWHEI-18Y

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) You have requested the Internal Photographs be held Confidential. In general, this Exhibit cannot be held Confidential without substantial justification. In my opinion, this requirement has not been met. Please provide a detailed rationale why Internal Photographs should be held Confidential.
- 2.) Please do a final double-check on the model numbers. There seems to be instances where both "...18Y" and "...18YT" are confused. Kindly do one last double check of your Exhibits.
- 3.) Please note that the FCC logo is not appropriate for this device. Only computers and computer peripherals which follow the DoC equipment authorization procedures are to use this mark.
- 4.) Please provide a tune-up procedure. This is required for all Licensed radio transmitters.
- 5.) Please note that your test procedure of 1.9.2 is in error. Only the TIA/EIA 603 substitution method is recognized by FCC for this test.
- 6.) The conducted spurious emissions test of 1.9.3 does not appear to follow the resolution bandwidth descriptions listed in TIA/EIA 603. Please address.
- 7.) What units would you like to show the RF power? Would you like to use Conducted or ERP values? Please note the 731 form does not indicate.
- 8.) Please provide an emission designator complete with necessary bandwidth on Form 731. Please provide a requested frequency tolerance on Form 731 too.
- 9.) Please provide the voltage and current through the final amplification stage as required under Part 2 of the Rules. If I have missed it, my apologies – please help me find it.

William H. Graff
President

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.