

Page

: 1 of 3 : Sep. 27, 2019 : VGYAP912C Issued date FCC ID

Radiated Spurious Emission Setup Configurations

Above 1GHz





Underwriters Laboratories Taiwan Co., Ltd.Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000


Facsimile (FAX) :+886-3-583-7948




: 2 of 3 : Sep. 27, 2019 : VGYAP912C Page

Issued date FCC ID

Below 1GHz





Underwriters Laboratories Taiwan Co., Ltd.
Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000
Facsimile (FAX) :+886-3-583-7948



Page

: 3 of 3 : Sep. 27, 2019 : VGYAP912C Issued date FCC ID

AC Power Line Conducted Emission Setup Configurations





Underwriters Laboratories Taiwan Co., Ltd.
Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948