Appendix C

Date: 2009-06-30


Test report no.: 60.870.9.009.01F Model no.: MBP30BU (Baby Unit)


Photos of EUT – Internal EUT Photos






Page 1 of 8
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.






Page 2 of 8
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.







Page 3 of 8
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.







Page 4 of 8
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.






Page 5 of 8
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.







Page 6 of 8
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.





Page 7 of 8
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.





Page 8 of 8
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Shatin, Hong Kong.