


Appendix C

Date: 2013-03-25
Report No.: 60.870.12.008.01F
Model No.: MBP43BU



Photo of EUT – Internal EUT Photos



Appendix C

Date: 2013-03-25
Report No.: 60.870.12.008.01F
Model No.: MBP43BU



Photo of EUT – Internal EUT Photos



Appendix C

Date: 2013-03-25
Report No.: 60.870.12.008.01F
Model No.: MBP43BU



Photo of EUT – Internal EUT Photos



Appendix C

Date: 2013-03-25
Report No.: 60.870.12.008.01F
Model No.: MBP43BU

Photo of EUT – Internal EUT Photos



Appendix C

Date: 2013-03-25
Report No.: 60.870.12.008.01F
Model No.: MBP43BU

Photo of EUT – Internal EUT Photos

