## **Techtronic Cordless GP**

115 Innovation Way Anderson, SC 29621 U.S.A. Tel. 864-360-3359

## For the FCC SDoC Procedure

The following Equipment adapt FCC SDoC Procedure according to FCC part 2.906:

Product Name: JOBSITE RADIO

Brand Name: RIDGID Model Number: R84089

Report Number: BL-SZ2240790-401

FCC ID: VMZR84089

It's herewith confirmed to comply with the requirements of FCC Part 15 Rules.

Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference, and
- (2) This device must accept any interference received, including interference that may cause undesired operation.

It is understood that each unit marketed is identical to the device as tested, and any changes to the device that could adversely affect the emission characteristics will require retest.

The following importer / responsible party in United States:

Not Available at Certification Stage

Company Name: Techtronic Cordless GP

Company Address: 115 Innovation Way, Anderson, South Carolina, United States 29621

Telephone: (864) 360-3359

Fax: (864) 965-6274

Person is responsible for marking this declaration: Becky Yan

John Collins	Director Manager Regulatory Affairs
Name (Full name )	Position / Title
JoSoli	2022/6/21
Legal Signature	Date

 Ersteller:
 D. Brandhorst
 Revision:
 00

 Erstelldatum:
 07.03.2008
 Datum:
 00.00.00

 Seite 1 von 1
 00.00.00
 Seite 1 von 1