

Test report No. Page

Issued date FCC ID : 11354882H-A : 1 of 12

: August 17, 2016 : VPYLB1AD

## **RADIO TEST REPORT**

**Test Report No.: 11354882H-A** 

**Applicant** 

Murata Manufacturing Co., Ltd.

**Type of Equipment** 

Communication Module

Model No.

: Type1AD

FCC ID

: VPYLB1AD

**Test regulation** 

FCC Part 15 Subpart C: 2016

(Class II permissive change)

\*Maximum Peak Output Power Test only

**Test Result** 

: Complied

- 1. This test report shall not be reproduced in full or partial, without the written approval of UL Japan, Inc.
- 2. The results in this report apply only to the sample tested.
- 3. This sample tested is in compliance with the above regulation.
- 4. The test results in this report are traceable to the national or international standards.
- 5. This test report must not be used by the customer to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government.
- 6. This test report covers Radio technical requirements. It does not cover administrative issues such as Manual or non-Radio test related Requirements. (if applicable)

Date of test:

July 11, 2016

Representative test engineer:

Ken Fujita

Engineer Consumer Technology Division

Approved by:

Takayuki Shimada

Engineer

Consumer Technology Division



This laboratory is accredited by the NVLAP LAB CODE 200572-0, U.S.A. The tests reported herein have been performed in accordance with its terms of accreditation. \*As for the range of Accreditation in NVLAP, you may refer to the WEB address, http://japan.ul.com/resources/emc accredited/

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11354882H-A
Page : 2 of 12
Issued date : August 17, 2016
FCC ID : VPYLB1AD

**REVISION HISTORY** 

Original Test Report No.: 11354882H-A

| Revision        | Test report No. | Date               | Page<br>revised | Contents |
|-----------------|-----------------|--------------------|-----------------|----------|
| -<br>(Original) | 11354882H-A     | August 17,<br>2016 | -               | -        |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |
|                 |                 |                    |                 |          |

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11354882H-A
Page : 3 of 12
Issued date : August 17, 2016
FCC ID : VPYLB1AD

| CONTENTS  | PAGE |
|---|------|
| SECTION 1: Customer information                     | 4    |
| SECTION 2: Equipment under test (E.U.T.)            | 4    |
| SECTION 3: Test specification, procedures & results |      |
| SECTION 4: Operation of E.U.T. during testing       |      |
| SECTION 5: Antenna Terminal Conducted Tests         |      |
| APPENDIX 1: Test data                               | 10   |
| Maximum Peak Output Power                           |      |
| Average Output Power                                |      |
| APPENDIX 2: Test instruments                        | 12   |

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11354882H-A
Page : 4 of 12
Issued date : August 17, 2016
FCC ID : VPYLB1AD

### **SECTION 1:** Customer information

Company Name : Murata Manufacturing Co., Ltd.

Address : 10-1, Higashikotari 1-chome, Nagaokakyo-shi, Kyoto 617-8555 Japan

Telephone Number : +81-75-955-6736 Facsimile Number : +81-75-955-6634 Contact Person : Motoo Hayashi

### **SECTION 2:** Equipment under test (E.U.T.)

### 2.1 Identification of E.U.T.

Type of Equipment : Communication Module

Model No. : Type1AD

Serial No. : Refer to Section 4, Clause 4.2

Rating : DC 3.3V Receipt Date of Sample : July 5, 2016 Country of Mass-production : Japan, China

Condition of EUT : Engineering prototype

(Not for Sale: This sample is equivalent to mass-produced items.)

Modification of EUT : No Modification by the test lab

### 2.2 Product Description

### **General Specification**

Clock frequency(ies) in the system : 37.4MHz

Specification of WLAN (IEEE802.11b/g/n)

| Type of radio               | Wireless LAN (IEEE802.11b/g) | Wireless LAN (IEEE802.11n) |  |  |  |
|-----------------------------|------------------------------|----------------------------|--|--|--|
|                             |                              | 2.4G Band SISO (20M Band)  |  |  |  |
| Equipment Type              | Transceiver                  |                            |  |  |  |
| Frequency of Operation      | 2412MHz - 2462MHz            |                            |  |  |  |
| Bandwidth & Channel spacing | Bandwidth: 20MHz             |                            |  |  |  |
|                             | Ch spacing: 5MHz             |                            |  |  |  |
| Type of Modulation          | 11b: DSSS                    | OFDM                       |  |  |  |
|                             | 11g: OFDM                    |                            |  |  |  |
| Antenna Type / Antenna Gain | Monopole Antenna: -1.8dBi    |                            |  |  |  |
| Power Supply (inner)        | DC 3.3V                      |                            |  |  |  |
| Operating temperature range | -20 to                       | +70 deg. C                 |  |  |  |

<sup>&</sup>lt;Contents of the change from original model>

Specification was changed from the original model as follows:

The radio specification is identical to the original.

Therefore only Maximum Peak Output Power Test was performed in this report.

# UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test Report Number of original model is 10602907H-A (issued by UL Japan, Inc.).

<sup>\*</sup>Low power setting value of IEEE802.11b was added.

Test report No. : 11354882H-A
Page : 5 of 12
Issued date : August 17, 2016
FCC ID : VPYLB1AD

### **SECTION 3:** Test specification, procedures & results

### 3.1 Test Specification

Test Specification : FCC Part 15 Subpart C

FCC part 15 final revised on April 6, 2016.

Title : FCC 47CFR Part15 Radio Frequency Device Subpart C Intentional Radiators

Section 15.207 Conducted limits

Section 15.247 Operation within the bands 902-928MHz,

 $2400\hbox{-}2483.5MHz, and 5725\hbox{-}5850MHz$ 

### 3.2 Procedures and results

| Item  | Test Procedure   | Specification      | Worst margin | Results  | Remarks   |  |  |
|---|------------------|--------------------|--------------|----------|-----------|--|--|
|   |                  | FCC: Section       |              |          |           |  |  |
| Maximum Peak  | Guidance v03r05  | 15.247(b)(3)       |              |          |           |  |  |
| Output Power  |                  |                    | See data     | Complied | Conducted |  |  |
| Output 1 ower   | IC: RSS-Gen 6.12 | IC: RSS-247 5.4(4) |              |          |           |  |  |
| Note: UL Japan, Inc.'s EMI Work Procedures No. 13-EM-W0420 and 13-EM-W0422. |                  |                    |              |          |           |  |  |
|   |                  | <u> </u><br>/0422. |              |          |           |  |  |

<sup>\*</sup> In case any questions arise about test procedure, ANSI C63.10: 2013 is also referred.

### FCC Part 15.31 (e)

The EUT has the power supply regulator. However one of the input voltages to RF part doesn't go through the regulator. The stable voltage will be supplied by the end product, which will be required to have a power supply regulator. Therefore, the EUT complies with the requirement.

### FCC Part 15.203 Antenna requirement

It is impossible for end users to replace the antenna, because it is soldered on the circuit board. Therefore, the equipment complies with the antenna requirement of Section 15.203/212.

### 3.3 Addition to standard

| Item         | Test Procedure  | Specification | Worst margin | Results | Remarks   |
|--------------|-----------------|---------------|--------------|---------|-----------|
| 99% Occupied | IC: RSS-Gen 6.6 | IC: -         | N/A          | -       | Conducted |
| Bandwidth    |                 |               |              |         |           |

Other than above, no addition, exclusion nor deviation has been made from the standard.

### 3.4 Uncertainty

### **EMI**

The following uncertainties have been calculated to provide a confidence level of 95 % using a coverage factor k = 2. Is EMC Lab.

|        | Antenna terminal test Uncertainty (+/-) |   |        |         |           |          |               |  |
|--------|---|---|--------|---------|-----------|----------|---------------|--|
| Po     | wer meter                               | Conducted emission and Power density Conducted emission |        |         |           |          |               |  |
| Below  | Above                                   | Below   | 1 GHz  | 3 GHz   | 18 GHz    | 26.5 GHz | Channel power |  |
| 1 GHz  | 1 GHz                                   | 1 GHz   | -3 GHz | -18 GHz | -26.5 GHz | -40 GHz  |               |  |
| 0.9 dB | 1.0 dB                                  | 1.4 dB  | 1.7 dB | 2.8 dB  | 2.8 dB    | 2.9 dB   | 2.6 dB        |  |

## UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11354882H-A
Page : 6 of 12
Issued date : August 17, 2016
FCC ID : VPYLB1AD

### 3.5 Test Location

UL Japan, Inc. Ise EMC Lab. \*NVLAP Lab. code: 200572-0 4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN Telephone: +81 596 24 8999, Facsimile: +81 596 24 8124

| Test site                  | ite IC Registration Number Width x Depth x Height (m) Size of reference ground plane (m) / horizontal conducting plane |                   | Other rooms | Maximum<br>measuremen<br>t distance |      |
|----------------------------|--|-------------------|-------------|-------------------------------------|------|
| No.1 semi-anechoic chamber | 2973C-1  | 19.2 x 11.2 x 7.7 | 7.0 x 6.0   | No.1 Power<br>source room           | 10 m |
| No.2 semi-anechoic chamber | 2973C-2  | 7.5 x 5.8 x 5.2   | 4.0 x 4.0   | -                                   | 3 m  |
| No.3 semi-anechoic chamber | 2973C-3  | 12.0 x 8.5 x 5.9  | 6.8 x 5.75  | No.3 Preparation room               | 3 m  |
| No.3 shielded room         | -  | 4.0 x 6.0 x 2.7   | N/A         | -                                   | -    |
| No.4 semi-anechoic chamber | 2973C-4  | 12.0 x 8.5 x 5.9  | 6.8 x 5.75  | No.4 Preparation room               | 3 m  |
| No.4 shielded room         | -  | 4.0 x 6.0 x 2.7   | N/A         | -                                   | -    |
| No.5 semi-anechoic chamber | -  | 6.0 x 6.0 x 3.9   | 6.0 x 6.0   | -                                   | -    |
| No.6 shielded room         | -  | 4.0 x 4.5 x 2.7   | 4.0 x 4.5   | -                                   | -    |
| No.6 measurement room      | -  | 4.75 x 5.4 x 3.0  | 4.75 x 4.15 | -                                   | -    |
| No.7 shielded room         | -  | 4.7 x 7.5 x 2.7   | 4.7 x 7.5   | -                                   | -    |
| No.8 measurement room      | -  | 3.1 x 5.0 x 2.7   | N/A         | -                                   | -    |
| No.9 measurement room      | -  | 8.8 x 4.6 x 2.8   | 2.4 x 2.4   | -                                   | -    |
| No.11 measurement room     | -  | 6.2 x 4.7 x 3.0   | 4.8 x 4.6   | -                                   | -    |

## 3.6 Test data, Test instruments, and Test set up

Refer to APPENDIX.

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11354882H-A
Page : 7 of 12
Issued date : August 17, 2016
FCC ID : VPYLB1AD

## **SECTION 4:** Operation of E.U.T. during testing

## **4.1 Operating Mode(s)**

Test operating mode was determined as follows according to "Section 1 of 6 802.11 a/b/g/n testing - Managing Complex Regulatory Approvals - " of TCB Council Workshop October 2009.

| Mode  | Remarks*   |  |  |  |  |  |
|---|--|--|--|--|--|--|
| IEEE 802.11b (11b)                                    | 11Mbps, PN9  |  |  |  |  |  |
| *The worst condition was determined based on the tes  | *The worst condition was determined based on the test result of Maximum Peak Output Power (Mid |  |  |  |  |  |
| Channel)  |  |  |  |  |  |  |
| *Power of the EUT was set by the software as follows; |  |  |  |  |  |  |
| Power settings: 11b: 13dBm                            |  |  |  |  |  |  |
|   |  |  |  |  |  |  |

Software: version 5.90.230.2

\*This setting of software is the worst case.

Any conditions under the normal use do not exceed the condition of setting.


### \*The details of Operating mode(s)

| Test Item                  | Operating Mode | Tested frequency |
|----------------------------|----------------|------------------|
| Maximum Peak Output Power, | 11b Tx         | 2412MHz          |
| _                          |                | 2437MHz          |
|                            |                | 2462MHz          |

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11354882H-A
Page : 8 of 12
Issued date : August 17, 2016
FCC ID : VPYLB1AD

## 4.2 Configuration and peripherals



<sup>\*</sup> Cabling and setup(s) were taken into consideration and test data was taken under worse case conditions.

**Description of EUT** 

| Description of Le I |                      |              |               |                                   |         |  |  |
|---------------------|----------------------|--------------|---------------|-----------------------------------|---------|--|--|
| No.                 | Item                 | Model number | Serial number | Manufacturer                      | Remarks |  |  |
| A                   | Communication Module | Type1AD      | 1             | Murata Manufacturing Co.,<br>Ltd. | EUT     |  |  |
| В                   | Jig                  | -            | -             | Murata Manufacturing Co.,<br>Ltd. | -       |  |  |
| С                   | Laptop PC            | FMV-C8230    | R7305017      | FUJITSU                           | -       |  |  |
| D                   | AC Adapter           | FMV-AC312    | CA1007-0930   | FUJITSU                           | -       |  |  |

List of cables used

| No. | Name       | Length (m) | Shield     |            | Remarks |
|-----|------------|------------|------------|------------|---------|
|     |            |            | Cable      | Connector  |         |
| 1   | Flat Cable | 0.1        | Unshielded | Unshielded | -       |
| 2   | DC Cable   | 3.0        | Unshielded | Unshielded | -       |
| 3   | USB Cable  | 2.0        | Shielded   | Shielded   | -       |
| 4   | DC Cable   | 1.8        | Unshielded | Unshielded | -       |
| 5   | AC Cable   | 2.0        | Unshielded | Unshielded | -       |

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11354882H-A
Page : 9 of 12
Issued date : August 17, 2016
FCC ID : VPYLB1AD

## **SECTION 5: Antenna Terminal Conducted Tests**

### **Test Procedure**

The tests were made with below setting connected to the antenna port.

| Test               | Span | RBW | VBW | Sweep<br>time | Detector    | Trace | Instrument used     |
|--------------------|------|-----|-----|---------------|-------------|-------|---------------------|
| Maximum Peak       | -    | -   |     | Auto          | Peak/       | -     | Power Meter         |
| Output Power       |      |     |     |               | Average *1) |       | (Sensor: 50 MHz BW) |
| *1) Reference data | •    |     |     | •             | •           |       |                     |

The test results and limit are rounded off to two decimals place, so some differences might be observed.

Test data : APPENDIX

Test result : Pass

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11354882H-A
Page : 10 of 12
Issued date : August 17, 2016
FCC ID : VPYLB1AD

## **APPENDIX 1:** Test data

## **Maximum Peak Output Power**

Test place Ise EMC Lab. No.3 Measurement Room

Report No. 11354882H Date 07/11/2016

Temperature/ Humidity 23 deg. C / 40% RH

Engineer Ken Fujita Mode 11b Tx

| Freq. | Reading | Cable | Atten. | Result |       | Limit |      | Margin |
|-------|---------|-------|--------|--------|-------|-------|------|--------|
|       |         | Loss  |        |        |       |       |      |        |
| [MHz] | [dBm]   | [dB]  | [dB]   | [dBm]  | [mW]  | [dBm] | [mW] | [dB]   |
| 2412  | 5.63    | 1.77  | 10.03  | 17.43  | 55.32 | 30.00 | 1000 | 12.57  |
| 2437  | 5.99    | 1.78  | 10.03  | 17.80  | 60.19 | 30.00 | 1000 | 12.20  |
| 2462  | 5.72    | 1.79  | 10.03  | 17.53  | 56.64 | 30.00 | 1000 | 12.47  |

Sample Calculation:

Result = Reading + Cable Loss (including the cable(s) customer supplied) + Attenuator

### 2437MHz

| Rate   | Reading | Remark |
|--------|---------|--------|
| [Mbps] | [dBm]   |        |
| 1      | 8.42    |        |
| 2      | 8.73    |        |
| 5.5    | 8.63    |        |
| 11     | 9.02    | *      |

\*: Worst Rate

All comparizon were carried out on same frequency and measurement factors.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11354882H-A
Page : 11 of 12
Issued date : August 17, 2016
FCC ID : VPYLB1AD

## **Average Output Power**

Test place Ise EMC Lab. No.3 Measurement Room

Report No. 11354882H Date 07/11/2016

 $Temperature/\ Humidity \hspace{1cm} 23\ deg.\ C\ /\ 40\%\ RH$ 

Engineer Ken Fujita Mode 11b Tx

[AV]

11b **11Mbps** 

|   |       | PS      |       |        |        |       |       |      |        |
|---|-------|---------|-------|--------|--------|-------|-------|------|--------|
| Г | Freq. | Reading | Cable | Atten. | Result |       | Limit |      | Margin |
|   |       |         | Loss  |        |        |       |       |      |        |
|   | [MHz] | [dBm]   | [dB]  | [dB]   | [dBm]  | [mW]  | [dBm] | [mW] | [dB]   |
| Г | 2412  | 1.83    | 1.77  | 10.03  | 13.63  | 23.06 | 30.00 | 1000 | 16.37  |
|   | 2437  | 1.96    | 1.78  | 10.03  | 13.77  | 23.80 | 30.00 | 1000 | 16.23  |
|   | 2462  | 1.97    | 1.79  | 10.03  | 13.78  | 23.89 | 30.00 | 1000 | 16.22  |

Sample Calculation:

Result = Reading + Cable Loss (including the cable(s) customer supplied) + Attenuator

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11354882H-A
Page : 12 of 12
Issued date : August 17, 2016
FCC ID : VPYLB1AD

## **APPENDIX 2:** Test instruments

**Test equipment** 

| Control No. | Instrument                  | Manufacturer     | Model No     | Serial No  | Test Item | Calibration Date * Interval(month) |
|-------------|-----------------------------|------------------|--------------|------------|-----------|------------------------------------|
| MOS-19      | Thermo-Hygrometer           | Custom           | CTH-201      | 0001       | AT        | 2015/12/08 * 12                    |
| MSA-15      | Spectrum Analyzer           | Agilent          | E4440A       | MY46187105 | AT        | 2015/11/11 * 12                    |
| MPM-12      | Power Meter                 | Anritsu          | ML2495A      | 0825002    | AT        | 2016/06/06 * 12                    |
| MPSE-17     | Power sensor                | Anritsu          | MA2411B      | 0738285    | AT        | 2016/06/06 * 12                    |
| MTW-09      | Torque wrench               | HUBER+SUHNER     | 74 Z-0-0-21  | 72676      | AT        | 2015/03/05 * 36                    |
| MAT-22      | Attenuator(10dB)<br>1-18GHz | Orient Microwave | BX10-0476-00 | -          | AT        | 2016/03/18 * 12                    |
| MCC-138     | Microwave cable             | HUBER+SUHNER     | SUCOFLEX 102 | 37953/2    | AT        | 2015/10/08 * 12                    |
| MMM-10      | DIGITAL HITESTER            | Hioki            | 3805         | 051201148  | AT        | 2016/01/18 * 12                    |

The expiration date of the calibration is the end of the expired month.

All equipment is calibrated with valid calibrations. Each measurement data is traceable to the national or international standards.

As for some calibrations performed after the tested dates, those test equipment have been controlled by means of an unbroken chains of calibrations.

Test Item: AT: Antenna Terminal Conducted test

**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN