


LBUA0VG2BP Label Design and Location



There is no space to describe the FCC ID Number. Therefore, it is described on the manual and package.



: Murata Logo mark

2BP

: Model Type name

MS1119001 : Inspection Number



: Pin 1 Marking



: 2D Code

LBUA0VG2BP Label Design and Location

The character size is
4 points or more.



FCC ID:VPYLB2BP IC: 772C-LB2BP HVIN:LBUA0VG2BP

This device complies with part 15 of FCC Rules and Industry Canada's licence-exempt RSSs. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

FCC CAUTION

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.