

Hwa Yao Technologies Co.,Ltd

December 11, 2007

Federal Communications Commission
Authorization and Evaluation Division

FCC ID: VQ2-UTO-08-UTP-14

The Antenna is with N connector inside by waterproof glue sealed, user couldn't change the connector by self and there is no guarantee on the performance if you destroy it by the external force.

Sincerely,

李曼曼

Hwa Yao Technologies Co.,Ltd